

PRIMARY CORNER DESCRIPTION Sec. Cor. for 15, 16, 21 and 22

Alias_____	Description_____
Alias_____	Description_____
Alias_____	Description_____
Alias_____	Description_____

Original - Nathaniel Ford, under Contract #44 dated May 30, 1854 (DCSO records, Vol. 15 Page 6531)

-----

Set post cor. of secs.15, 16, 21 and 22, from which

- A Laurel 10" dia., bears S.12°E., 75 lks. dist.
- A Laurel 12" dia., bears N.60°E., 62 lks. dist.
- A Laurel 14" dia., bears N.87°W., 50 lks. dist.
- A Laurel 16" dia., bears S.62½°W., 39 lks. dist.

GLO survey by Hans W. Thielsen under Group #346, Surveyed, April/May 1957 (DCSO records Vol. 28 Page(s) 12155)

-----  
Point for the cor. of secs. 15, 16, 21 and 22, at proportionate distance; there is no remaining evidence of the original corner.

Set and Iron post, 3 ft. long, 2" dia., 28" in the ground with brass cap mkd. T29S R7W

S 16	S 15
S 21	S 22
1957	

from which

- A Fir 59" dia., bears N.45°E., 88 lks. dist., mkd. T29S R7W S15 BT.
- A Fir 18" dia., bears S.61°E., 46 lks. dist., mkd. T29S R7W S22 BT.
- A Fir 28" dia., bears S.39°W., 31 lks. dist., mkd. T29S R7W S21 BT.
- A Fir 30" dia., bears N.47°W., 21 lks. dist., mkd. T29S R7W S16 BT.

BLM resurvey by John M. Jelley, under Group #346, Surveyed, Aug./Oct. 1966 (DCSO records Vol. 34 Page(s) 14292)

-----  
Point for the cor. of secs. 15, 16, 21 and 22, at proportionate distance; there is no remaining evidence of the original corner.

From this point, the cor. of secs. 15, 16, 21 and 22, erroneously reestablished by Thielsen, in 1957, bears South, 0.197 chs. dist., set, marked and witnessed as described in official record. I remove the iron post, and at the corner point

Reset the iron post, 36" long, 2" dia., 28" in the ground, with brass cap mkd. T 29 S R 7 W

S 16	S 15
S 21	S 22
1966	
1957	

(Cont. Next Page)

TOWNSHIP 29 RANGE 07 POINT IDENTIFIER # 400400

PRIMARY CORNER DESCRIPTION Sec. Cor. for 15, 16, 21 and 22

Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

from which bearing trees mkd. by Thielsen  
A Fir 59" dia., bears N.58°E., 74 lks. dist., with healed blaze.  
A Fir 33" dia., bears S.24°W., 49 lks. dist., with healed blaze.  
and new bearing trees  
A Fir 24" dia., bears S.51°E., 81 lks. dist., mkd. T29S R7W S22 BT.  
A Fir 7" dia., bears N.67°W., 11 lks. dist., mkd. T29S R7W S16 BT.  
I destroy the marks on the 1957 bearing trees to the SE. and NW.

Fd. OK, May, 1981, Howard Johnstone, M 87-75

Howard Johnstone, LS #498 - For: Roseburg Lumber Co. - June 29, 1984 - C.S. File 58/296 and M 97-54, Oct. 2, 1984

-----  
Found - 1957/1966 BLM cadastral brass cap.  
7" D.Fir N.67°W., 7.3 ft., good condition.  
59" D.Fir N.58°E., 48.8 ft. now a stump.  
24" D.Fir S.51°E., 53.5 ft., good condition.  
33" D.Fir S.24°W., 32.3 ft., good condition.  
New BT - 20" D.Fir S.84°E., 74.7 ft. scribed "T29S R7W S22 BT".  
NW of section 15 has been recently clear cut. No remaining trees suitable for BTs. Corner is about 300 ft. West of road at corner of recent clearcut.

Fd ok Set 6 ft steel post 2 ft. N.88°W., by D. Edwards - 4/2014 - M167-73