

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 7 and 8

Alias	Description
_____	_____
_____	_____
_____	_____
_____	_____

GLO survey by W.H. Byars, Deputy Surveyor under contract # 152 survey dated June 3, 1871 (DCSO records Vol. 20 Page(s) 8461)

-----  
Set 1/4 sec. post, from which  
A Fir 6" dia., bears S.50°E., 116 lks. dist.  
A Laurel 6" dia., bears S.70°W., 110 lks. dist.

GLO survey by Carl S. Nicklin, Deputy Surveyor, under Contract #664, dated May 23, 1896 (DCSO records Vol. 20 Page(s) 8532-33)

-----  
The 1/4 sec. corner, which I find to be entirely destroyed except the bearing tree in sec. 8, from which I reestablish this corner as follows:  
Set a Madrona post 3 ft. long 4" sq., 24" in the ground for 1/4 sec. corner, marked 1/4 S on W. face, from which  
A Fir 12" dia., bears S.50°E., 116 lks. mkd. 1/4 S BT.  
A Madrona 6" dia., bears N.72°W., 88 lks. mkd. 1/4 S BT.

BLM resurvey by Larry Evans, Cadastral Surveyor under Group #736, surveyed May/June 1971 (DCSO records Vol. 37 Page(s) 15339)

-----  
The 1/4 sec. cor., determined at record bearing and distance from the remaining original 1871 bearing tree redescribed in 1897:  
A Fir 33" dia., bears S.50°E., 116 lks. with healed blaze.  
At the corner point  
Set an iron post, 28" long, 2 1/2" dia., 24" in the ground, with brass cap mkd: T 32 S R 4 W  
1/4  
S 7 S 8  
1071  
from which a new bearing tree  
A Fir 21" dia., bears N.61 3/4°W., 54 lks. mkd. 1/4 S7 BT.  
The corner falls in a ravine, drains S.50°W.

Fd. OK, Nov. 1990, M 111-12