

Resurvey of South Boundary T. 24 S., R. 8 W.

CHAINS
40.00

Set a post $3\frac{1}{2}$ ft. long, 3 ins. sq., 24 ins. in the ground for $\frac{1}{4}$ sec. cor., marked $\frac{1}{4}$ S. on N. face, from which

A Maple, 6 ins. diam., bears N.20°E., 37 lks. dist., marked $\frac{1}{4}$ S B T.

A Hemlock, 7 ins. diam., bears S.34°E., 29 lks. dist., marked $\frac{1}{4}$ S B T.

61.60 The cor. to Tps. 24 and 25 S., Rs. 8 and 9 W., which is a post 4 ins. sq., 2 ft. above ground, marked T 24 S S 31 on NE., R 8 W S 6 on SE., T 25 S S 1 on SW., and R 9 W S 36 on NW faces, with 6 notches on each edge, from which

A Cedar, 10 ins. diam., bears N.20°E., 30 lks. dist., marked T 24 S R 8 W S 31 B T.

A Maple, 8 ins. diam., bears S.40°E., 10 lks. dist., marked T 25 S R 8 W S 6 B T.

A Fir, 48 ins. diam., bears S.56°W., 68 lks. dist., marked T 25 S R 9 W S 1 B T.

A Fir, 60 ins. diam., bears N.60°W., 24 lks. dist., marked T 24 S R 9 W S 36 B T.

Land, broken.

Soil, 3rd and 4th rate.

Heavily timbered with Fir, Hemlock and Cedar, 61.60 chs.

Dense undergrowth of vinemaple, hemlock, hazel and salal, 61.60 chs.

May 18th, 1894.

Retracement of West Bdy. T. 24 S., R. 8 W.,
Same Deputy and Contract.

The error discovered in the chaining on the South boundary, accounts for the error in departure in the closing made on the North boundary, but does not account for the error in latitude. Believing this error to exist in the West boundary, I run North from the cor. to Tps. 24 and 25 S., Rs. 8 and 9 W.,