

Retracement of West Bdy. T. 24 S., R. 8 W.

CHAINS

retracing the West boundary Tp. 24 S., R. 8 W. I found no material error, either in chaining or alignment, until I passed the  $\frac{1}{4}$  sec. cor. on the West bdy. Sec. 19, where I found the North  $\frac{1}{4}$  mile on the West bdy. Sec. 19, to be 4.93 chs. short. I continued North and found the chaining on each mile along the West bdys. of Secs. 18, 7 and 6 to be short. The error in chaining will require a resurvey of the West bdys. of Secs. 18, 19, 7 and 6, and the re-establishment of a new set of cors. on which to close the sub-divisions of T. 24 S., R. 8 W. I, therefore, commence at the  $\frac{1}{4}$  sec. cor. on the West bdy. Sec. 19, (my chaining having previously shown that this cor. is correctly located) which is a Fir tree, 20 ins. diam., marked  $\frac{1}{4}$  S on W. face, from which

- A Fir, 20 ins. diam., bears N.75°E., 13 lks. dist., marked  $\frac{1}{4}$  S B T.
- A Fir, 16 ins. diam., bears S.30°W., 25 lks. dist., marked  $\frac{1}{4}$  S B T.

Resurvey of West Boundary of T. 24 S., R. 8 W.,  
Same Deputy and Contract.

North, on West boundary Sec. 19.

Va. 20°E.

Over broken land, through heavy timber and dense undergrowth.

30.00 A Spring branch, 3 lks. wide, flows NW.

35.07 The old established cor. to Secs. 18, 19, 13 and 24, which is a Fir, 24 ins. diam., marked T 24 S S 18 on NE., R 8 W S 19 on SE., R 9 W S 24 on SW., and S 13 on NW. faces, with 3 notches on N and S sides, from which

- A Fir, 16 ins. diam., bears N.55°E., 25 lks. dist., marked T 24 S R 8 W S 18 B T.