

Retracement of Subdivision of T. 24 S., R 9 W.

CHAINS

3.50 Cross a spur sloping NW.

29.15 Branch, 2 lks. wide, course S.W.

30.70 Branch, 1 lks. wide, course S.

39.53 The cor. of secs. 3, 4, 9 and 10 which is a post firmly set, marked and witnessed as described by the Surveyor General, bears South, 43 lks. dist.

The true bearing of this line is therefore S.89°22'W.

The old post being greatly decayed, I destroy, and at the same point, set a fir post, 3 ft. long, 4 ins. sq., 24 ins. in the ground, for cor. of secs. 3, 4, 9 and 10 mkd. T 24 S S 3 on NE., and

R 9 W S 4 on NW. face, with 5 notches on S., and 3 notches on E. face.

Land, mountainous.

Soil, 3rd rate.

Timber, fir.

Undergrowth, vine maple, sakal, rhododendron, Oregon grape and huckleberry.

Land, mountainous, heavily timbered or covered with dense undergrowth, 78.50 chs.

August 21, 1905

Sec. 9 not closing in limits, after retracing my work and finding it correct; In order to locate the error, I proceed as follows:

At cor. now common to secs. 3 and 4 only.

Thence I run.

West, on a blank line between secs. 4 and 9.

Over mountainous land through heavy timber and dense undergrowth.

7.50 Branch, 3 lks. wide; course NW.

39.19 The $\frac{1}{2}$ sec. cor. which is a post firmly set, marked and witnessed as described by the Surveyor General, except the tree bearing N. 89°E., is 39 lks. dist. instead of 29 lks. as noted, bears South, 123 lks. dist.