

**UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT**

FIELD NOTES

OF THE

REHABILITATION OF THE 1/4 SECTION CORNER

OF SECTIONS 8 AND 9,

TOWNSHIP 24 SOUTH, RANGE 6 WEST,

OF THE WILLAMETTE MERIDIAN,

IN THE STATE OF OREGON.

EXECUTED BY

Timothy J. Moore, Cadastral Surveyor

Robert H. Browning, Surveying Technician

Under Special Instructions dated July 13, 1979, approved July 17, 1979,
and Supplemental Special Instructions
dated May 20, 1985, approved May 24, 1985,
which provided for the surveys included under Group No. 1000,
and assignment instructions dated June 16, 1999.

Survey commenced June 21, 1999

Survey completed June 21, 1999

T. 24 S., R. 6 W., Willamette Meridian, Oregon

FEET	
	<p>The following field notes describe the rehabilitation of the 1/4 sec. cor. of secs. 8 and 9, township 24 south, range 6 west, Willamette Meridian, Oregon, as provided for in the Special Instructions dated July 13, 1979, and Supplemental Special Instructions dated May 20, 1985, under Group 1000, Oregon, "Rehabilitation of corner Points, Without Remonumentation, When Suitable Monument Exists."</p> <p>The rehabilitation of the 1/4 sec. cor. of secs. 8 and 9, was made at the request of the Roseburg District Manager for the administrative purposes of the Bureau of Land Management.</p> <p>The mean magnetic declination as noted in the 1963 White and McDonald resurvey is 20¼° East.</p> <hr/> <p align="center">Rehabilitation of the 1/4 Section Corner of Sections 8 and 9, T. 24 S., R. 6 W., Willamette Meridian, Oregon</p> <hr/> <p align="center">(Rehabilitating a corner established by William R. Whipple, U.S. Deputy Surveyor, in 1891, and remonumented by C. Albert White, and Norman J. McDonald, Cadastral Surveyors, in 1963)</p> <hr/> <p>The 1/4 sec. cor. of secs. 8 and 9, determined at record bearing and distances from the remains of the original bearing trees and the bearing trees mkd. by White, and McDonald, (the iron post set by White and McDonald is laying on the ground near the position of the original corner) from which the remains of the original bearing trees</p> <p>A roothole, bears N. 65¼° E., 31.0 ft. dist., with uprooted and decayed fir, 62 ins. diam., no visible mks., laying alongside.</p> <p>A sawed and decayed hemlock stump, size indeterminate, bears N. 37½° W., 12.5 ft. dist., with axe mks.</p> <p>and the remains of the bearing trees mkd. by White and McDonald</p> <p>A yew, 17 ins. diam., bears S. 54¼° E., 26.4 ft. dist., with scribe marks 4 S9 BT visible on partially healed blaze.</p> <p>A sawed and badly decayed cedar stump, size indeterminate, bears N. 71¼° W., 54.8 ft. dist., no mks. visible.</p> <p>At the corner point</p>

Rehabilitation of the 1/4 Section Corner of Sections 8 and 9,
T. 24 S., R. 6 W., Willamette Meridian, Oregon

FEET	
	<p>Reset the iron post, 28 ins. long, 2½ ins. diam., 26 ins. in the ground, with brass cap mkd.</p> <p style="text-align: center;">T 24 S R 6 W 1/4 S 8 S 9 1963</p> <p>Add the marks 1999 to the bottom of the brass cap.</p> <p>from which a new bearing tree</p> <p style="padding-left: 40px;">A fir, 15 ins. diam., bears N. 50° W., 3.0 ft. dist., mkd. 1/4 S8 BT, with a magnetic nail, 2½ ins. long, ¼ ins. diam., driven at the base on right side-center.</p> <p>Deposit a magnet in a white plastic case at the base of the stainless steel post.</p> <p>Corner is located West, 7.0 ft., of a creek 1 ft. wide, course N. 10° W.</p> <hr/>