

PRIMARY CORNER DESCRIPTION E. 1/4 Cor. for Sec. 24 only, T19-9

Alias	Description
_____	_____
_____	_____
_____	_____
_____	_____

BLM survey by Thomas A. Tillman; Robert L. Holm & Floyd A. Brooks, Cadastral Surveyors, under Group #307, surveyed May 1957/Sept. 1958 - (DCSO records Vol. 31 Page(s) 13021-22)

Point for the ¼ sec. cor. of sec. 24 only, on the E. bdy. of T19S R9W., at midpoint between closing corners.
Set an iron post 3 ft. long, 2" dia., 28" in the ground with brass cap mkd:
T 19 S
¼ S 24
R 9 W
1957

from which
A Fir 72" dia., bears N.40°W., 26 lks. dist. mkd. ¼ S24 BT.
A Hemlock 14" dia., bears S.33°W., 95 lks. dist. mkd. ¼ S24 BT.

BLM Resurvey by John P. Farnsworth, Cadastral Surveyor, under Group #1076, surveyed Sept. 1981/April 1983 - (DCSO records Vol. 45 Page(s) 17469)

(38.13 chs.) Point for the ¼ sec. cor. of sec. 24 only, T19S R9W.
From this point, the ¼ sec.cor. of sec. 24 only, erroneously positioned by Tillman, Holm and Brooks, bears N.88°50'W., 0.039 chs. dist., monumented with an iron post, 2" dia., firmly set, projecting 10" above ground, with brass cap mkd. and witnessed as described in the official record.
I remove the iron post, and at the true corner point, Reset the iron post 36" long, 2" dia., 30" in the ground with brass cap mkd:
T 19 S
R 9 W
¼ S 24
1983
1957

from which bearing trees mkd. by Tillman, etal
A Hemlock 16" dia., bears S.35°W., 98 lks. dist. with illegible scribe marks visible on partially healed blaze.
A Fir 77" dia., bears N.47°W., 29 lks. dist. with healed blaze.
and new bearing trees:
A Cedar 68" dia., bears S.48½°W., 99 lks. dist. mkd. ¼ S24 BT.
A Maple 10" dia., bears N.57°W., 45 lks. dist. mkd. ¼ S24 BT.