

PRIMARY CORNER DESCRIPTION WC 1/4 Cor Secs 20 & 21

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GLO survey by C.M. Collier, Deputy Surveyor, under Group #580 dated June 23, 1891 - (DCSO records Vol. 2 Page(s) 528)

Set post, 4 ft. long, 3" sq., 24" in the ground, for 1/4 sec. cor., mkd: 1/4 S on W face; from which

A Fir, 24" dia., bears S.88 3/4°E., 63 lks., mkd: 1/4 S BT

A Fir, 30" dia., bears N.43°W., 25 lks., mkd: 1/4 S BT

BLM Resurvey by Marvin J. Lytle and Palmer Norseth, under Group #298, surveyed May/Aug. 1952 - (DCSO records Vol. 31 Page(s) 12938)

Point for the 1/4 sec. cor. of secs. 20 & 21 as determined from the orig. BTs:

A Fir, 37" dia., bears N.43°W., 25 lks., with old blaze on SE face.

A stump hole of a fallen Fir bears S.88°45'E., 63 lks.

At the corner point

Set an iron post, 3' long, 1" dia., 6" in the ground to solid rock and in a mound of stone to top, with brass cap mkd:

$$\begin{array}{c} \frac{1}{4} \\ S\ 20 \mid S\ 21 \\ 1952 \end{array}$$

from which

A Fir, 20" dia., bears N.70 1/4°E., 102 lks., mkd: 1/4 S21 BT.

A Fir, 35" dia., bears S.30°45'W., 18 lks., mkd: 1/4 S20 BT.

Robert Cook - For: Oxbow Timber 1 LLC - 2/2018 - M174-18

Found - Position lies in a very steep slide. My zenith angle was 130°. All remains of the 1952 monument are destroyed.

I managed to set a 4" "MagSpike" in a root at the corner position but it was very unstable and I set a witness corner.

Set - 5/8" x 30" rebar with a 2" aluminum cap stamped "1/4 S20 S21 2018 WC" with an arrow aiming North, on line S.00°11'56"E. 95.00 ft on the ridge. A steel post was driven 0.5' West.

17" Hemlock N.52°E. 8.8 ft. scribed "WC" above "BT".

16" D.Fir S.47°E. 6.8 ft. scribed "WC" above "BT".

21" D.Fir S.12°E. 15.1 ft. scribed "WC" above "BT".

18" D.Fir S 52°W 18.5 ft. scribed "WC" above "BT".

Fd. Alum. cap & 4 BTs 4/2020 by R Cook - M176-67

Fd. Alum. cap & 4 BTs 1/2021 by R Cook - M179-6

