

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 33 & 34

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO survey by C.M. Collier, Deputy Surveyor, under Group #580 dated June 23, 1891 - (DCSO records Vol. 2 Page(s) 517)

Fir, 18" dia., on W. side of top of ridge, which I mark for 1/4 sec. cor., mkd: 1/4 S on W face; from which
A Fir, 24" dia., bears N.68°E., 27 lks., mkd: 1/4 S BT
A Fir, 16" dia., bears S.63°W., 33 lks., mkd: 1/4 S BT

BLM Resurvey by Marvin J. Lytle and Palmer Norseth, under Group #298, surveyed May/Aug. 1952 - (DCSO records Vol. 31 Page(s) 12923-4)

The 1/4 sec. cor. of secs. 33 & 34, mkd by the root hole of the orig. tree corner which is fallen but still shows a healed blaze on the former W. side, from which the orig. BTs:

A Fir, 45" dia., bears N.68°E., 27 lks., mkd: with a healed blaze facing SW.
A Fir, 27" dia., bears S.37 1/2°W., 45 lks., showing a healed blaze facing NE. (Rec. S.63°W., 33 lks.)

At the corner point
Set an iron post, 3' long, 1" dia., 27" in the ground, with brass cap mkd:

1/4
S 33 | S 34
1952

from which
A Fir, 15" dia., bears N.17°45'W., 70 lks., mkd: 1/4 S33 BT.
A Fir, 30" dia., bears S.46 1/4°E., 25 lks., mkd: 1/4 S34 BT

David Edwards - For: Oxbow Timber 1 LLC - 1/2015 - M170-32

Found - BLM BC
43" Fir S.46 1/4°E., 16.5'
32" Fir N.17 3/4°W., 46.2'
Both with healed blaze.
Set - 6 ft. steel post 2' north.