

PRIMARY CORNER DESCRIPTION E. 1/4 Cor. for Sec. 36 only

Alias	Description
Alias	Description
Alias	Description
Alias	Description

GLO survey by C.M. Collier, Deputy Surveyor, under Group #580 dated June 23, 1891 - (DCSO records Vol. 2 Page(s) 499)

Set post 4 ft. long, 4" sq., 24" in the ground, for 1/4 sec. cor. marked 1/4 S on W. face; from which

A Fir 18" dia., bears S.60°W., 26 lks. dist. mkd. 1/4 S BT.

A Fir 12" dia., bears S.45 1/2°E., 23 lks. dist. mkd. 1/4 S BT.

BLM Resurvey by Norman Price and Thomas Tillman, Cadastral Engineers, under Group #284, Surveyed June/Sept. 1949 - (DCSO records Vol. 31 Page(s) 12950-51)

The 1/4 sec. cor. of sec. 36 only, determined at the record bearing from the original SE. bearing tree and at the record bearing and distance from the original SW. bearing tree, as follows:

A Fir 36" dia., bears S.45 1/4°E., 22 lks. dist., plainly blazed and healed, but center of tree gutted by fire. (Rec. distance 23 lks.)

A Fir stump, badly burned and decayed, 36" dia., bears S.60°W., 26 lks. dist., with no marks remaining.

At the corner point

Set an iron post, 3 ft. long, 1" dia., 28" in the ground, with brass cap mkd: 1/4 S 36
1949

from which new bearing trees:

A Fir 24" dia., bears S.46 1/2°W., 161 lks. dist. mkd. 1/4 S36 BT.

A Fir 36" dia., bears N.64°W., 35 lks. dist. mkd. 1/4 S36 BT.