

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 21 & 28

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO Survey by Henry L. Chandler, U.S. Deputy Surveyor, under Contract #705 dated April 14, 1899 - (DCSO records Vol. 1 Page(s) 428-29)

Set a Fir post, 3 ft. long, 3" sq., 24" in the ground, for ¼ secs. cor. mkd: ¼ S21 on N and 28 on S faces; from which
A Fir, 4" dia., bears N.80°E., 40 lks., mkd: ¼ S BT.
A Fir, 6" dia., bears S.45°W., 15 lks., mkd: ¼ S BT.
Old cor. bears North 13 lks., I destroy it.
* 1899 survey is a corrective resurvey of Chandler's 1895 survey. The Orig. 1895 survey was not accepted but some corners were accepted on a case by case basis. Per Eugene's & Coos Bay's BLM offices.

BLM dependent resurvey by Donald R. Beck & Peter A. Peterson, Cadastral Surveyors, under Group #307, surveyed April 1968/Aug. 1976 (DCSO records Vol. 37 Page(s) 15455)

Point for ¼ sec. cor. of secs. 21 & 28, at proportionate distance; there is no remaining evidence of the orig. corner. Set an iron post, 28" long, 2½" dia., 24" in the ground, with brass cap marked:
¼ $\frac{S\ 21}{S\ 28}$
T19S R9W
1969

from which
A Hemlock, 20" dia., bears N.44°W., 24 lks., mkd: ¼ S21 BT
A Hemlock, 7" dia., bears S.44°E., 45 lks., mkd: ¼ S28 BT.

Ernesto Alvarado, U.S.F.S. - Witnesses: Colin Long & Carol Dickinson - March 12, 1982 - C.S. File 61/32-4

Found - 1969 BLM brass cap 7" above ground in good condition, marked: S21 S28 ¼ T19S R9W 1969
29" Hemlock bears N.45½°W. 15.4 ft., scribing visible ¼ S21.

SE BT has been destroyed by road construction.
New BT - 12" Hemlock bears S.9°W., 43.8 ft. mkd "¼ S28 CS BT".

Location-Go south on FS Rd. #23 approx. 0.7 miles past junction with BLM Rd. #20-9.1 to Rd. #19-22.2. Then go to the end (turn right at fork). Corner is 40 ft. west of the road. Location poster on east side of road. Corner bears S.84°W., distance 77 ft.