

TOWNSHIP 19 RANGE 10 POINT IDENTIFIER # 300140

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 32 & 33

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GLO Survey by Henry L. Chandler, U.S. Deputy Surveyor, under Contract #705 dated April 14, 1899 - (DCSO records Vol. 1 Page(s) 294)

-----  
The 1/4 sec. cor., established on former survey\*, which is a sandstone, 15x10x6 ins. 11" in the ground, marked 1/4 on N face; from which

A Fir, 14" dia., bears S.45°E., 15 lks., mkd: 1/4 S33 BT.

A Fir, 16" dia., bears S.9°W., 5 lks., mkd: 1/4 S32 BT.

\* 1899 survey is a corrective resurvey of Chandler's 1895 survey. The Orig. 1895 survey was not accepted but some corners were accepted on a case by case basis. Per Eugene's & Coos Bay's BLM offices.

Douglas Co. Surveyors Office - Vernon "Ray" Tracy - J. Heritage - V. Perron - May 1968 - C.S. File 53/66-37

-----  
Found - Orig. cor. stone 24x15x10", mkd: "1/4" tipped over.  
Orig. 14" now 26" Fir, alive, S.45°E., 9.9 ft., show good scar. We rescribe "1/4 S33 CS BT"

No trace of other Orig. BT.

Set - Brass cap at cor. mkd: COUNTY SURVEYORS T19S R10W  
OFFICE 1969 1/4 S 33 | S 32

Brass cap set in hole where stone was tipped out of.  
28" D.Fir S.41°W., 7.3 ft., mkd: 1/4 S32 CS BT

This corner lies on steep SE slope in very dense brush.

Cor. fd. good condition - 10/24/1978 by E. Alvarado, USFS & Dep. Douglas Co. Surveyor's Office, C.S. File 60/17-17