

PRIMARY CORNER DESCRIPTION Cor. Secs 11, 12, 13, & 14

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GLO Survey by Henry L. Chandler, U.S. Deputy Surveyor, under Contract #705 dated April 14, 1899 - (DCSO records Vol. 1 Page(s) 279)

-----  
An Alder, 6" dia., for cor. of secs. 11, 12, 13, & 14, which I marked T19S S12 on NE, R10W S13 on SE, S14 on SW & S11 on NW sides, with 4 notches on S & 1 notch on E sides; from which

An Alder, 6" dia., bears N.68°E., 27 lks., mkd: T19S R10W S12 BT.

A Fir, 14" dia., bears S.38°E., 87 lks., mkd: T19S R10W S13 BT.

A Fir, 8" dia., bears S.8°W., 56 lks., mkd: T19S R10W S14 BT.

A Hemlock, 6" dia., bears N.18°W., 16lks., mkd: T19S R10W S11 BT.

Old cor. bears S.5°W., 15 lks., I destroy it.

\* 1899 survey is a corrective resurvey of Chandler's 1895 survey. The Orig. 1895 survey was not accepted but some corners were accepted on a case by case basis. Per Eugene's & Coos Bay's BLM offices.

-----  
Alan D. Reid, Forester - Lane Co. Restored Corners - Sept. 1958, Filed Feb. 8, 1971 - C.S. File 53/1-10

I find the orig. SE & SW BTs for the corner.

At the indicated position for the tree corner, is an old rotten stump with a 20" Alder beside it on the South. At the position for the NE BT is another Alder, badly broken & rotted. There is no sign of the NW Hemlock BT except a rotted stump. Corner is at the head of a ravine to the NE in large Alder area. Corner is about 4 ch. E of N-S spur ridge top, about 5 ch. north of E-W spur ridge.

At the corner point indicated by the remaining BTs, I drive an old Iron Well point, 1½x30", 18" above ground, under a 2' bank. This is beside the north edge of a 20" Alder which I bark scribe : on the NE - S12, on the NW - S11, on the SE - S13, on the SW - S14.

26" Fir, scribed S12FS, N.33°33'E., 92 lks.

Note - There are alder trees at the location of the corner and the NE orig. BT. There are no signs of the orig. markings on these, but they have the appearance of being sprouts from the broken stumps of the orig. trees. Pipe driven on the N side of the corner tree, pipe hidden by being under a 2 ft bank.

(Cont. next page)

PRIMARY CORNER DESCRIPTION Cor. Secs 11, 12, 13, & 14

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

Douglas Co. Surveyors Office - John Powell - W. Penley - Jack Heritage - Feb. 1971 - C.S. File 53/66-44

-----

Found - Alder corner tree now stump, scribe visible "S13",  
Iron Well point alongside stump. 1971  
26" D.Fir, now stump N.33½°E., 60.7 ft., some scribe  
marks visible, mostly grown over.  
Possible orig. Fir, 14" now 46", S.38°E., 57.4 ft.  
shows gaint scar. I do not open because corner is  
in clear-cut unit with no BTs available.

Set - Brass cap alongside Well Point & corner stump mkd:  
County Surveyor's Office T19S R10W  
1971 S 11 | S 12  
S 14 | S 13

Steel fence post set alongside Brass cap.

New Bearing stump & objects:  
30" D.Fir stump S.6°W., 38.7 ft., scribed T19S R10W  
S14 CS BT  
5/8" iron rod N.32°W., 30.8 ft.  
5/8" iron rod N.31°E., 37.0 ft.  
(Bearing & dist. between iron rods: S.80°W., 35.4')

Cor. Fd. good condition 11/7/1978 by E. Alvarado, USFS &  
Dep., Co. Surveyor's Office - C.S. File 60/17-22

Daniel Baker, LS 1978 - For: Margaret Crowell - Sept. 19,  
1988 - M 107-1 - See C.S. File 63/69 for Lane Co. Info.

-----

Found - Douglas Co. Brass cap. 1971  
24" Fir stump, N.35½°E., 61.5 ft.  
38" Fir stump, S.36½°E., 56.1 ft.  
30" Fir stump, S.6½°W., 39.0 ft.

Note - True corner point bears S.4°38'E., 1.30 ft. Lane Co.  
Survey data C.S. 24151 (1980)

BLM dependent resurvey by Robert W. Dahl, Cadastral Surveyor,  
under Group #1450, surveyed Aug. 1988/Oct. 1989 - (DCSO  
records Vol. 49 Page(s) 08778-79)

-----

The corner of secs. 11, 12, 13, & 14, monumented with the  
remains of the orig. cor. tree, an Alder snag, 20" dia., 1  
ft. high, no marks, from which the remains of the orig. BTS:  
A Fir stump, 46" dia., 6 ft. high bears S.37½°E., 83 lks.,  
with healed blaze. (Rec. S.38°E., 87 lks)

Cont. next page

PRIMARY CORNER DESCRIPTION Cor. Secs 11, 12, 13, & 14

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

A Fir stump, 30" dia., 6 ft. high bears S.6°W., 56 lks., with healed blaze. Remarked by Powell in 1971, with scribe marks T19S R10W S14 CS BT visible on unhealed blaze. (Rec. S.8°W.)  
 and the remains of a BT mkd. by Reid in 1958  
 A Fir stump, 26" dia., 10 ft. N.34½°E., 95 lks., with healed blaze.  
 and accessories established by Powell in 1971  
 An iron rod, 5/8" dia., firmly set, projecting 6" above ground, bears N.29°56'E., 57.8 lks.  
 An iron post, 1½" dia., firmly set, projecting 8' above ground, bears N.4°38'W., 2.0 lks., with brass cap mkd: T19S S11 S12 S 13 S14 R10W 1971, and with an iron pipe, 1½" dia., buried alongside.  
 The iron rod set to the NW was fd. lying loose on the ground.  
 At the corner point  
 Set a stainless steel post, 28" long, 2½" dia., 24" in the ground, & in center of corner tree with brass cap mkd;  
 T19S R10W  
 S 11 | S 12  
 S 14 | S 13  
 1988 from which  
 A Fir, 10" dia., bears S.5 3/4°E., 27½ lks., mkd: T19S R10W S13 BT.  
 A Fir, 11" dia., bears S.70¼°W., 25 lks., mkd: T19S R10W S14 BT.  
 A Fir, 10" dia., bears N.30°W., 20 lks., mkd: T19S R10W S11 BT.  
 Deposit white "DEEP-1" magnetic marker at base of stainless steel post.  
 Cor. is located on SE slope near the head of ravine drains NE

Daniel Baker, LS 1978 - For: Margaret Crowell - 5/1990 - M110-15 (Correcting survey M 107-1 )

-----  
 CONDITION REPORT ONLY  
 Found - Douglas Co. Brass cap. 1971  
 24" Fir stump, N.35½°E., 61.5 ft.  
 38" Fir stump, S.36½°E., 56.1 ft.  
 30" Fir stump, S.6½°W., 39.0 ft.  
 Note - True corner point bears S.4°38'E., 1.30 ft. At this point found a 1989 BLM brass cap & 3 new BTs:  
 10" Fir, S.5 3/4°E., 27½ lks.  
 12" Fir, S.70¼°W., 25 lks.  
 10" Fir, N.30°W., 20 lks.

Please note that this corner is on the Douglas Co. & Lane Co. line and Lane Co. Surveyor's Office may have more information concerning this corner.