

TOWNSHIP 20 RANGE 06 POINT IDENTIFIER # 100440

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Sec. 18; & 13, T20-6 1/2

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

**This corner is in Lane Co - See
Lane County for more information**

GLO survey by J. H. McClung, under Contract #173, dated July 20, 1872 - (DCSO records Vol. 2 Page(s) 548)

Set sandstone 18x13x7 ins. for 1/4 sec. corner.

BLM Resurvey by Harvey E. Wofford and Lester E. Fischer, Cadastral Surveyors, under Group #913, Surveyed Aug. 1976/Aug. 1978 - (DCSO records Vol. 40 Page(s) 16070-71)

The 1/4 sec. cor., reestablished at proportionate distance by John D. Venator, Registered Land Surveyor #278 in 1954, monumented with a steel steering gear shaft, 1" dia., firmly set, projecting 4" above ground. There is no remaining evidence of the original corner; therefore, this point is accepted as the best available evidence of the position of the original corner, from which the remains of the bearing trees mkd. by Venator:

A root hole, bears S.33°E., 28 lks. dist., with a down and decayed Hemlock alongside, 12" dia., no marks visible.

A root hole bears S.47°W., 40 lks. dist., with a down and decayed Hemlock alongside, 18" dia., no marks visible.

At the corner point

Set an iron post, 28" long, 2 1/2" dia., 22" in the ground, with brass cap mkd:

T 20 S
R 6 1/2 W R 6 W
1/4
S 13 | S 18
1978

from which new bearing trees:

A Hemlock 14" dia., bears N.27°E., 73 1/2 lks. dist., mkd. 1/4 S18 BT.

A Fir 33" dia., bears N.18°W. 62 lks. dist. mkd. 1/4 S13 BT.

Reset steel shaft and set a 5 ft. steel fence post alongside iron post.