

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GL0 survey by J.H. McClung under Contract #173 dated July 20, 1872 - (DCSO rec. Vol. 2 Page(s) 685

 Set post for corner to secs. 21, 22, 27, & 28; from which
 A Maple, 6" dia., bears N.25°E., 25 lks.
 A Dogwood, 6" dia., bears S.54°E., 18 lks.
 A Dogwood, 5" dia., bears N.45°W., 5 lks.
 A Maple, 3" dia., bears S.63°W., 20 lks.

BLM dependent resurvey by Marvin J. Lytle, Cadastral Surveyor under Group #293 dated May 1950, surveyed June/Aug. 1950 - (DCSO records Vol. 27 Page(s) 11322-3)

 The cor. of secs. 21, 22, 27, & 28, determined at the intersection of old blazed lines to the N, S, & W, & the remains of the orig. BTs:
 A Maple, 10" dia., bears N.25°E., 25 lks., showing a healed blaze facing SW, with core decayed.
 A Dogwood stump, bears S.54°E., 18 lks., badly decayed but showing an old blaze facing NW.
 A Dogwood stump and stool, bears N.45°W., 5 lks.
 There is no remaining evidence of the 3" Maple in the SW quadrant.
 At the corner point
 Set an iron post, 3' long, 2" dia., 30" in the ground, with brass cap marked:
 T 20 S R 6 W
 S 21 | S 22
 S 28 | S 27
 1950 from which
 A Fir, 13" dia. bears N.48°E. 39 lks. mkd: T20S R6W S22 BT
 A fir, 42" dia., bears S.86¼°E., 120 lks., mkd: T20S R6W S27 BT.
 A Fir, 60" dia., bears S.53°W., 119 lks., mkd: T20S R6W S28 BT.
 A Fir, 24" dia., bears N.30°45'W., 53 lks., mkd: T20S R6W S21 BT.

Lane County Restored corner report, signed William L. Wilt, 6/20/1961, Land Agent - Rec'd 11/1962 - C.S. File 53/1-8 & 52/104 & C.S. 53-102-3

<u>1950 GL0 Rec.</u>	<u>1961 report</u>
Brass cap	Found
13" Fir N.48°E., 39 lks.	32" Fir OK
42" Fir S.86¼°E., 120 lks.	Gone, destroyed by logging
60" Fir S.53°W., 119 lks.	Now stump, scribing visible
24" fir N.30¼°W., 53 lks.	Removed in road construction

continued next page

TOWNSHIP 20 RANGE 06 POINT IDENTIFIER # 400300

PRIMARY CORNER DESCRIPTION Cor. Secs. 21, 22, 27, & 28

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

Retracement notes:

Plates, "W" nails, 20° Declination
32" Fir N.49°E., 33.4 ft.
16" Fir S.72°E., 23.4 ft.
44" Fir stump S.52°W., 77.3 ft.
48" Fir N.30°W., 76.3 ft.

Douglas Co. Surveyors Office - Milo Godfrey - Vernon Tracy
- Clete Putnam - Feb. 15, 1962 - C.S. File 49/89-17

Correction of field notes on Sec. Cor. set by Cadastral
survey of 1950 (Note: Rec'd the Lane Co. Report 11/1962)

Found - Pipe & brass cap as described in Gov't notes

Record BTs - Gov't notes

13" Fir N.48°E., 25.7 ft.
24" Fir N.30°45'W., 35.0 ft.
42" Fir S.86¼°E., 79.3 ft.
60" Fir S.53°W., 78.5 ft.

Trees as found in field

Orig. 13" Fir (now 18") S.75°E., 25.1 ft.
Orig. 24. Fir (now 32") N.48°E., 35.0 ft.
(These 2 trees show very plain healed over scars)
60" Fir stump S.53°W., 79.0 ft.
Other tree not found.

NOTE - There is a typed note added to the old system of
typed cor. renewals, alongside of a report for the ¼ cor. to
secs. 19 & 30 but with an arrow pointing towards this report,
the note says "See corner information in C.S. File No. 53/1
for cor. set in 1937 by Lane Co." There is not a 1937 corner
report for this sec. cor. in that file but there is a 1937
report for the ¼ to secs. 19 & 30 in C.S. File 52/104, which
is also a file of cor. reports from Lane Co. (10/31/2001 DCSO)

Corner card received from Roseburg BLM, Barry Williams, dated
4/4/1972 - C.S. File 54/22-16

Found - US GLO brass cap 1950. Corner was on upper East edge
of rocked road cut bank which dropped out. Corner
lying along edge of road. (East side)

DF 36" N.49°E., 33.4 ft., scribe grown over, bark
visible /-/, BLM BT, WTCO. poster.

DF 18" E 35 ft., scribe grown over, bark visible [^]_W

Added to card & hand written on typed 1962 DCSO corner report:
6/1972 We reset GLO BC in place on rock bank. NO new BTs
To reach: From Smith River Co. Rd. up BLM Elk Crk road 10-16-
32, 20-6-21.1 to put rocked spur across Sec. 28 to NE cor.

continued next page

TOWNSHIP 20 RANGE 06 POINT IDENTIFIER # 400300

PRIMARY CORNER DESCRIPTION Cor. Secs. 21, 22, 27, & 28

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

BLM Dependent Resurvey by A Bert Skeesick, Cadastral Surveyor and Robert H Browning, Survey Tech, Under Group No. 2268, Surveyed March/July 2009 - DCSO records Vol. 57 Pages 22630-1

The cor. of secs. 21, 22, 27, & 28, perpetuated by Wilt, in 1961, determined at record bearing and distance from the remains of the original bearing trees

A maple, 6" dia., bears N.25°E., 16.5 ft., with no marks visible.

A dogwood, 10" dia., bears S.45¾°E., 11.9 ft., with no marks visible. (Record, S.54°E.)

and the remains of bearing trees mkd. by Lytle

A fir, 46" dia., bears N.48°E., 33.7 ft., with a healed blaze. (Record, 25.7 ft.)

A fir, 43" dia., bears S.53°W., 78.5 ft., with fragmentary scribe marks visible on a partially healed blaze. and bearing tree mkd. by Wilt

A fir, 67" dia., bears N.30¾°W., 78.0 ft., with a healed blaze.

(Note: The iron post set by Lytle in 1950, was disturbed by road construction and found wired to a rebar driven nearby in an unrelated position.)

At the corner point

Reset the iron post, 30" long, 2" dia., 14" in the ground, in sandstone bedrock, with brass cap mkd.

T20S R6W
S 21 | S 22
S 28 | S 27
1950

from which

A fir, 19" dia., bears S.50¾°W., 65.2 ft., mkd. T20S R6W S28 BT.

Corner is located on a steep E. cut bank of a dirt road, 12 ft. wide, bears N.5°E. and S.5°W.

Ronald L Rice - For: Silver Butte Timber Co.; Seneca Jones Timber Co.; & Oxbow Timber 1 LLC - Nov. 2014 - M168-66

Found - GLO BC dated 1950 with the following accessories:
6" Maple bears N.25°E., 16.5' - no marks
10" Dogwood bears S.45¾°E., 11.9' - no marks
46" D.Fir bears N.48°E., 33.7' - healed face
43" D.Fir stump bears S.53°W., 78.5' - scribing visible.
67" D.Fir bears N.30¾°W., 78.0' - healed face
19" D.Fir bears S.50¾°W., 65.2' - healed face
Steel post adjacent to corner