

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 9 & 10

Alias	Description

A decayed fir snag, 35" dia., bears N.11°W., 33.0 ft., no marks visible.
and new bearing trees
A fir, 10" dia., bears N.28¾°E., 15.9 ft., mkd. ¼ S10 BT.
A fir, 16" dia., bears S.48½°W., 8.5 ft., mkd. ¼ S9 BT.
There is a steel fence post alongside the corner.
Each new bearing tree has a 2½"x ¼" magnetic nail (Mag Nail) driven at the base right side-center.

BLM Dependent Resurvey by Kenneth W. Saveland, Cadastral Surveyor, under Group No. 2670, Surveyed May 2012/June 2013 - (DCSO records Vol. 58 Pages 23043-4)

The ¼ sec. cor. of secs. 9 and 10, monumented with an iron post, 1" dia., firmly set, projecting 8 ins. above ground, with a brass cap (properly) mkd. from which the remains of BTs mkd. by Glenn, et al., in 1967
A decayed fir stump, 47" dia., bears S.36°E., 46.9 ft. , with scribe marks 4 S visible on partially healed blaze.
A decayed fir stump, 21" dia., bears N.11°W., 33.0 ft., with no marks.
and the bearing trees mkd. by Graham in 2005
A fir, 14" dia., bears N.28¾°E., 15.9 ft. , with a healed blaze and a magnail on right side center.
A fir, 19" dia., bears S.48½°W., 8.5 ft. , with a healed blaze and a magnail on right side center.
A steel fence post is alongside the cor.
NAD 1983 (2011)
Latitude: 43°50'31.99"N. Longitude: 123°38'24.19"W.

Ronald L Rice - For: Oxbow Timber 1 LLC - April 2016 - C.S. File 65/92-6

Found - 1954 GLO brass cap with the following accessories:
47" D.Fir stump bears S.36°E., 46.9' - scribing visible.
21" D.Fir stump bears N.11°W., 33.0' - no marks
15" D.Fir bears N.28¾°E., 15.9' - scribing visible
21" D.Fir bears S.48½°W., 8.5' - scribing visible
New BTs- This survey 9" Alder bears N.27°W., 20.8' - bark scribed ¼ S9 BT
7" D.Fir bears S.0½°E., 19.4' - blazed, scribed ¼ S10 BT steel post adjacent to corner.