

PRIMARY CORNER DESCRIPTION 1/4 Cor. Sec. 18 only (North)

| Alias | Description |
|-------|-------------|
| Alias | Description |
| Alias | Description |
| Alias | Description |

GLO survey by Wm. Thiel under contract 567 dated Feb. 16, 1891 - (DCSO records Vol. 1 Page(s) 334)

-----  
A Vine Maple, 3" dia., which I marked for ¼ sec. cor. ¼ S on N face; from which

A fir, 36" dia., bears S.76°E., 100 lks., mkd: ¼ S BT.

A fir, 36" dia., bears N.66½°W., 12 lks., mkd: ¼ S BT.

GLO resurvey by Fred Mensch, U.S. Cadastral Engineer; under Instructions dated April 8, 1920, Group 56 - (DCSO records Vol. 1 Page(s) 391-2)

-----  
Intersect the old ¼ sec. cor. orig. a vine maple, 3" dia., now nearly obliterated by decay, witnessed as described by the surveyor general. Hereafter this cor. will refer to sec.18 only. I obliterate marks on former BT N of line, and at exact corner point, in cavity of decayed corner tree. Set an iron post, 3 ft. long, 1" dia., 27" in the ground, for ¼ sec. cor. of sec. 18 only, with brass cap marked:

¼ S 18  
1921

from which

(Old BT) A fir, 40" dia., bears S.76°E., 100 lks., mkd: ¼ S18 BT.

(New BT) A hemlock, 14" dia., bears S.78°W., 50 lks., mkd: ¼ S18 BT.

(The 1/4 Cor. Sec. 7 (South) bears N.89°04'W., 2.50 chains)

BLM dependent resurvey by Thomas A. Tillman & Joseph S Gawron, under Group # 306, Surveyed May 1953 - Oct. 1954 (DCSO recs Vol. 29 Page(s) 12531)

-----  
The ¼ sec. cor. of sec. 18 only, remonumented by Mensch, in 1921, with an iron post, 1" dia., 8" above ground, firmly set, but badly rusted, with brass cap (properly) marked. At the corner point, in place of the rusted iron post, Set an iron post, 3 ft. long, 1" dia., 28" in the ground, with brass cap marked:

¼ S 18  
1954

from which

A fir, 50" dia., bears N.65°W., 15 lks., marked ¼ S BT on bark blaze. (A Thiel BT; rec. bears N.66½°W., 12 lks.)

A hemlock, 24" dia., bears S.60°W., 50 lks., marked ¼ S18 BT on unhealed blaze. (A Mensch BT, record bearing S.78°W.)

continued next page

TOWNSHIP 20 RANGE 09 POINT IDENTIFIER # 140500

PRIMARY CORNER DESCRIPTION 1/4 Cor. Sec. 18 only (North)

|             |                   |
|-------------|-------------------|
| Alias _____ | Description _____ |
| Alias _____ | Description _____ |
| Alias _____ | Description _____ |
| Alias _____ | Description _____ |

The fir marked by Mensch in SE quadrant is uprooted & decayed, and no suitable tree is now available.  
Deposit the old iron post at the base of the new one.  
(The 1/4 Cor. Sec. 7 (South) bears N.88°09'W., 2.48 chains)

BLM corrective remonumentation and rehabilitation of certain corners by Edith M Forkner, Cadastral Surveyor, under Group #2000, surveyed Feb. 2006/March 2009 - (DCSO records Vol. 58 Page(s) 23112)

-----  
The ¼ sec. cor. of sec. 18 only, on the N. bdy. of the sec., monumented with an iron post, 1" dia., firmly set, projecting 16" above ground, with brass cap (properly) mkd. from which the remains of an original bearing tree  
A decayed fir stump, 42" dia , bears N.65°W., 11.3. ft., no marks visible. (Record, 9.9 ft.)  
and new bearing trees  
A fir, 11" dia, bears East, 11.5 ft., mkd. ¼ S18 BT.  
A fir, 8" dia., bears S.28°W., 10.0 ft., mkd. X BT.  
The 1921-22 iron pipe, badly rusted, 1" dia., firmly set, projecting 6" above ground, with concrete core and brass cap missing, was reset by Tillman and Gawron in 1953-54, alongside the cor. and found alongside.