

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 25 & 26

Alias	Description

GLO survey by Wm. Thiel under contract 567 dated Feb. 16, 1891 - (DCSO records Vol. 1 Page(s) 351)

Set post, 4 ft. long, 5" sq., 24" in ground, for 1/4 sec. cor. marked 1/4 S on W face; from which

- A fir, 36" dia., bears N.51°W., 20 lks., mkd: 1/4 S BT.
- A fir, 42" dia., bears N.83°E., 45 lks., mkd: 1/4 S BT.

This post stands almost on top of a flat ridge; small timber has been burnt & now covers the ground.

BLM dependent resurvey by Thomas A. Tillman & Joseph S Gawron, under Group # 306, Surveyed May 1953 - Oct. 1954 (DCSO recs Vol. 29 Page(s) 12466)

The 1/4 sec. cor. of secs. 25 & 26, determined from the orig. BTs as follow:

- A fir, 62" dia., bears N.83°E., 45 lks., with blaze opened & no marks remaining on charred face.
- A fir, 50" dia., bears N.51°W., 20 lks., with blaze opened & no marks remaining on charred face.

At the corner point

Set an iron post, 3 ft. long, 1" dia., 28" in the ground, with brass cap marked:

1/4
S 26 | S 25
1954

from which new BTs,

- A hemlock, 8" dia., bears S.76°E., 11 lks., mkd: 1/4 S25 BT.
- A hemlock, 8" dia., bears S.43°W., 49 lks., mkd: 1/4 S26 BT.

The 1/4 sec. cor. is located on top of indistinct spur ridge, bears NE & SW.

Douglas Co. Surveyors Office - Vernon "Ray" Tracy - Jack Heritage - V. Perron - 5/15/1969 - C.S. File 53/66-106

Found - 1954 Cad. brass cap out of place as determined from BTs as follows:

- Orig. now 62" Fir N.83°E., 29.7' sawed stump - burned no scribe visible.
- Orig. now 50" Fir N.51°W., 13.7' sawed stump - 1954 rescribed visible.
- 1954 8" Hemlock S.76°E., 7.3 ft. now shattered stump. Scribe visible .

SW Hemlock down & out of place.

Reset - Brass cap at a cor. point & set steel fence post along side.

New BT - 12" Cedar N.79°W., 98.5' mkd: S26 CS BT

No trees close to East. This cor. lies 30 ft. East of cold water Creek Access Road. cont. next pg

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 25 & 26

Alias	Description

BLM remonumentation of Orig. corner points by Wm. W. Glenn & James E. Jelley, Cadastral Surveyors, under Group #s 350 & 635, surveyed April & May 1967 (DCSO records Vol. 37 Page(s) 15383-4)

The 1/4 sec. cor. of secs. 25 & 26, monumented with an iron post, 1" dia., firmly set, projecting 6" above ground, with brass cap (properly) marked from which the orig. BTs

A fir 57" dia., bears N.83°E., 47 1/2 lks., with healed blaze (rec. 45 lks.)

A fir, 55" dia., bears N.51°W., 26 lks., no marks visible on burned blaze. Rescribed 1/4 S26 BT on new blaze. (Rec. 20 lks.)

and the remains of the BTs marked in 1954

A hemlock, 10" dia., bears S.73 1/2°E., 11 1/2 lks., with fragmentary scribe marks visible on partially healed blaze. (Rec. S.76°E., 11 lks.)

A dead hemlock, 10" dia., bears S.46°W., 49 lks., with healed blaze. (Rec. S.43°W.)

Set a 6 ft. steel fence post alongside the iron post.

Fd. Ok by Les Roberts, 2/27/1984 - M96-20

Douglas Co. Surveyors Office - L.E. Monrean, Deputy - Randall Smith - Stephen Flause - March 22, 1984 - C.S. File 62/16-3

Found - 1954 US GLO properly marked brass cap on 1" IP protruding 6" above ground.

36" fir, now a 48" stump 5 ft. high with a burnt single blaze, bears N.49°W., 16.1 ft. (Rec. N.51°W., 13.2 ft.) Orig. BT.

42" fir, now a 57" stump 5 ft. high with a burnt single blaze bears N.83°E., 30.6 ft. (Rec. 29.7 ft. Orig. BT.

8" hemlock now a 1 ft. high shattered stump with rotted out blaze bears S.73 1/2°E. 7.6 ft. (1954 BT)

17" Cedar now a 17" dia., 2 ft. high stump w/well healed double blaze bears N.79°W., 98.5 ft. 1969

New BTs- 5" D.Fir double blazed & scribed "1/4 S26 CS BT" bears S.51°W., 18.3 ft.

6" D.Fir double blazed & scribed "1/4 S25 CS BT" bears N.30°E., 34.7 ft.

Note - See also L.D. Roberts LS 1039 survey M96-20 for condition report.

This corner lies along gentle southeast slope covered with 10-15 year old reproduction.

Cont.

TOWNSHIP 20 RANGE 09 POINT IDENTIFIER # 600240

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 25 & 26

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

BLM corrective remonumentation and rehabilitation of certain corners by Edith M Forkner, Cadastral Surveyor, under Group #2000, surveyed Feb. 2006/March 2009 - (DCSO records Vol. 58 Page(s) 23087-8)

The ¼ sec. cor of secs 25 & 26, monumented with an iron post, 1" dia. , firmly set, projecting 4" above ground, with brass cap (properly) mkd.

from which the remains of the original bearing trees

A decayed fir stump, 56" dia. , bears N.83°E. , 31.4 ft., with no marks visible on open burned blaze.

A decayed fir stump, 40" dia., bears N.51°W., 17.2 ft., with no marks visible on decayed blaze.

and the remains of the BTs mkd. by the Douglas County Surveyor in 1969

A decayed cedar stump, 12" dia. , bears N.79°W., 98.5 ft., no marks visible.

and the remains of the BTs mkd. by the Douglas County Surveyor in 1984

A fir, 18" dia. , bears N.30°E., 34.7 ft. with a healed blaze.

A roothole bears S.51°W., 18.3 ft., with a down fir, 14" dia., lying alongside, with a healed blaze.

and a new bearing tree

A fir, 14" dia., bears S.50°W., 38.8 ft., mkd. ¼ S26 BT.