

PRIMARY CORNER DESCRIPTION Sec. Cor. for 8, 9, 16 and 17

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO survey by Harvey Gordon and Charles T. Gardner, Deputy Surveyors, under Contract #52 dated Feb. 17, 1855 (DCSO records Vol. 2 Page(s) 771)

Set post cor. of secs. 8, 9, 16 and 17, from which
A Fir 10" dia., bears N.13°W., 65 lks. dist.
A Fir 6" dia., bears S.42°W., 27 lks. dist.
A Fir 8" dia., bears S.72°E., 88 lks. dist.
A Hemlock 40" dia., bears N.77°E., 24 lks. dist.

Douglas Co. Surveyors Office - James Byron, Deputy and crew - Jan. 1969 - C.S. File 54/14-46A

Looked for, not found.
Logged and cleared many years ago. No trees or stumps old enough for orig. BTs.

BLM resurvey by Peter Peterson and Daniel Berry, Cadastral Surveyors under Group #756, surveyed Aug. 1971/June 1972 (DCSO records Vol. 36 Page(s) 15019-20)

Point for the sec. cor., at proportionate distance; there is no remaining evidence of the original corner.

Set an iron post, 28" long, 2 1/2" dia., 22" in the ground, with brass cap mkd:

T	21	S	R	4	W
	S	8		S	9
	S	17		S	16
					1972

from which
A Cedar 9" dia., bears N.24°E., 56 lks.
A Fir 7" dia., bears S.12°E., 6 lks, mkd. T21S R4W S16 BT.
A Fir 13" dia., bears S.45°W., 7 lks, mkd. T21S R4W S17 BT
A Fir 13" dia., bears N.20°W., 43 lks, mkd. T21S R4W S8 BT

Survey by Ronald Geisler - For: Champion International - March 27, 1990 - C.S. File 63/112-1

Found - 1972 BLM 3 1/4" brass cap on a 3" x 30" Iron pipe. BC/IP extending 20" above ground and very loose. Record distances to BTs were up to one foot in error.

Firmly RESET BC/IP at record distance from SE. and SW. BTs, extending 6" above ground, from which

11" Fir, bent trunk, bears S.12°E., 3.96 ft., closed face. (1972)

15" dead and leaning Fir, bears S.45°W., 4.63 ft., rotting face.

(Cont. Next Page)

