

TOWNSHIP 21 RANGE 04 POINT IDENTIFIER # 400500

PRIMARY CORNER DESCRIPTION Sec Cor for 9, 10, 15 and 16

| | |
|-------------|-------------------|
| Alias _____ | Description _____ |
| Alias _____ | Description _____ |
| Alias _____ | Description _____ |
| Alias _____ | Description _____ |

GL0 survey by Harvey Gordon and Charles T. Gardner, Deputy Surveyors, under Contract #52 dated Feb. 17, 1855 (DCSO records Vol. 2 Page(s) 766)

Set post cor. of secs. 9, 10, 15 and 16, from which
A Fir 80" dia., bears N.65°E., 50 lks. dist.
A Fir 10" dia., bears S.58°W., 47 lks. dist.
A Maple 8" dia., bears N.61°W., 22 lks. dist.
A Dogwood 9" dia., bears S.62°E., 22 lks. dist.

O.F. Thiel - For: Martin Anderson - Sept. 13, 1928 - Field Book 116 Pg. 36

Found marks on NE. stump and SE. tree (dead). Marked:
Hemlock 22" N.11°W., 10 (lks.; ft.?)
Fir 8", S.24°E., 42 (lks.; ft.?)
Corner is S. of the Pacific Hwy. about 2.50 on N. slope of hill.

Charles C. Bayles - July 1953 - C.S. File 41/183

Corner destroyed by road construction. Found original Fir, 80", N.69°E., 50 lks., blasted out. From stump hole, SET red stake at corner.
(Also see State Hwy. map filed as H-6)

Douglas County Surveyors Office - Milo E. Godfrey, Deputy - Nov. 9, 1964 - C.S. File 49/68-33

Looked for, not found.

Douglas County Surveyors Office - Vernon "Ray" Tracy and crew April 2, 1969 - C.S. File 54/14-36A

Found 1¼" I.R. on white lines bet. S. bound lands of I-5.
Set by O.S.H.D.?

BLM resurvey by Peter Peterson and Daniel Berry, Cadastral Surveyors under Group #756, surveyed Aug. 1971/June 1972 (DCSO records Vol. 36 Page(s) 15020)

The Sec. Cor., perpetuated and recorded by Bayles, in 1947, from original evidence no longer in existence monumented with an iron pipe 1" dia., firmly set, protruding 10" above ground.
At the corner point

(Cont. Next Page)

TOWNSHIP 21 RANGE 04 POINT IDENTIFIER # 400500

PRIMARY CORNER DESCRIPTION Sec Cor for 9, 10, 15 and 16

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

Set an iron post, 28" long, 2 1/2" dia., 22" in the ground,
with brass cap mkd:

T 21 S R 4 W
S 9 | S 10
S 16 | S 15
1972

from which new bearing trees

A Cedar 10" dia., bears S.12°E., 21 lks. dist. mkd. T21S
R4W S15 BT.

A Fir 17" dia., bears S.36°W., 23 lks. dist. mkd. T21S R4W
S16 BT.

No other trees available within limits.

Deposit the iron pipe alongside the iron post.

Douglas Co. Surveyors Office - L.E. Monrean, Deputy - Wit:
D.L. Stewart; T.R. Plouff - Aug. 31, 1981 - C.S. 61/27-35

Not found

Orig. post marker.

Axle set by OSHD set in 1947 survey.

Red top stake set by Bayles in 1953.

BLM brass cap or 1" iron pipe, 1972 resurvey.

1" Iron rod that was found by Tracy in 1969.

These monuments evidently destroyed by Hwy. construction.

Found:

5/8" x 30" I.Rod set by Eimstad in 1981. (See M 89-25)

This monument was set by use of State hwy field notes,
State hwy. map and found right of way monuments for
position control. The 1947 and 1950 field notes show
ties to the axle set in 1947 as well as evidence of
bearing tree information. (accompanying notes in C.S.
File 61/27)

The original survey notes were checked for collateral call
information.

The following were located:

The orig. notes for the line ran to the North, call for a
stream 12 lks. (7.92 ft.) wide, course North, 4 chains
(264 ft.) North of the corner. From Eimstad's iron
rod, we find a creek, 10 ft. wide, course West, bears
North, 267.2 ft. to center.

The East line calls for a creek, 3 lks. wide, (1.98 ft.)
at 4.75 chains (313.5 ft.) course N-W. We find a
stream 2 ft. wide, course N-W., bears East 321.8 ft. to
center.

The position of the destroyed 1972 BLM brass cap is approx.
N.62°W., 144.1 ft. (according to OSHD information). We are
not able to clarify the reason for the BLM accepting a 1"
dia. iron pipe for corner position as the Baylis visit in

(Cont. Next Page)

TOWNSHIP 21 RANGE 04 POINT IDENTIFIER # 400500

PRIMARY CORNER DESCRIPTION Sec Cor for 9, 10, 15 and 16

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

1953, indicates a red top stake set at corner position. A measurement was made by the BLM from the section corner to the West, the found 1" dia. iron pipe beared N.89°08'E., 70.13 chains, original records show N.89°44'E., 80.00 chains. At position of found 5/8" x 30" iron rod set by 1981 Eimstad survey, WE SET a 1" x 30" Iron pipe with attached brass cap stamped: Douglas County Surveyor

T 21 S R 4 W
S 9 | S 10
S 16 | S 15
1981

Monument protrudes 5" above ground. We place found iron rod along South edge of monument, flush with ground.

New BTs- A Maple 14" dia., blazed and scribed "T21S R4W S10 CS BT", bears N.73½°E., 305.5 ft.

A Fir 21" dia., blazed and scribed "T21S R4W S15 CS BT", bears S.60°E., 288.3 ft.

A Fir 8" dia., blazed and scribed "T21S R4W S16 CS BT", bears S.6°W., 275.0 ft.

A Fir 14" dia., blazed and scribed "T21S R4W S16 CS BT" bears S.81°W., 398.8 ft.

SEE ALSO C.S. 61/27-62 (ADDED 5/28/2020)

Fd. OK, Oct. 1990 - M 110-72

Found OK by D. Edwards, Oct. 1998 - M130-42

FD. Ok by Kris DeGroot 10/2006 - M146-46A