

TOWNSHIP 21 RANGE 04 POINT IDENTIFIER # 500400

PRIMARY CORNER DESCRIPTION Sec. Cor. for 14, 15, 22 and 23

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GL0 survey by Harvey Gordon and Charles T. Gardner, Deputy Surveyors, under Contract #52 dated Feb. 17, 1855 (DCSO records Vol. 2 Page(s) 759)

Set post corner of secs. 14, 15, 22 and 23, from which
A Fir 18" dia., bears S.70°W., 11 lks. dist.
A Fir 20" dia., bears S.20°E., 21 lks. dist.
A Fir 20" dia., bears N.40°E., 53 lks. dist.
A Cedar 8" dia., bears N.45°W., 38 lks. dist.

Douglas co. Surveyors Office - Milo E. Godfrey, Deputy -
Sept. 20, 1962 - C.S. File 49/42-63

(Renewal request card submitted by John F. Rice, dated Sept. 10, 1962 "Iron pipe in good shape but BT will be lost in a few years - 36" D.Fir N.56°W., 10 ft., rotten stump - should be capped and new BTs made before old BT is lost.")
accepted

Visit by Godfrey:

Found 1¼" Iron pipe.

Found 30" Fir stump, S.55°E., 10.5 ft. from iron pipe. Scribing visible "21S R4W" and "T". No trace of "B" before T, although lower face is all visible and sound, solid wood. Did not renew cor. This stump does not fit bearing or dist. for any orig. BT. No trace of any other BTs found. I do not believe this is an orig. BT. We have no record of a renewal in this office. According to Mr. Davis, Victor Olson, Curtin, Oregon may be able to give us additional information about this corner. Corner lies 1/2 mile East of the Lookout of Ward's Butte.

(in answer to inquiry from DCSO, Mr. Olson replies: Dear Sirs, We received your letter last week wanting some information about the corners of sec. 22. There is a half section established on the Ward Butte, you probably can back track to the North East corner. Yours Truly Victor Olson.)

BLM resurvey by James E. Jelley and Wayne L. Rogers, Cadastral Surveyors, under Group #1026, surveyed July 1980/March 1981 - (DCSO records Vol. 44 Page(s) 16960)

The Sec. Cor., reestablished by person(s) unknown, monumented with an iron post, 2" dia., firmly set, projecting 8" above ground, in wire fence, extending N. and S. This position has long been recognized as the corner of adjacent landowners, and is accepted as the best available evidence of the position of the original corner,
(Cont. Next Page)

TOWNSHIP 21 RANGE 04 POINT IDENTIFIER # 500400

PRIMARY CORNER DESCRIPTION Sec. Cor. for 14, 15, 22 and 23

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

from which the remains of a bearing tree mkd. by person(s) unknown:

A decayed Fir stump 34" dia., bears S.52°E., 16 lks. dist., with scribe marks 21 R4W T visible on opened blaze.

At the corner point

Set an iron post, 28" long, 2 1/2" dia., 22" in the ground, with brass cap mkd:

T 21 S R 4 W	
S 15	S 14
S 22	S 23
1980	

from which new bearing trees;

A Fir 15" dia., bears N.54½°E., 11 lks. dist. mkd. T21S R4W S14 BT.

A Fir 5" dia., bears S.22¼°E., 92 lks. dist., mkd. T21S R4W S23 BT.

A Fir 9" dia., bears S.29°W., 25 lks. dist., mkd. T21S R4W S22 BT.

A Fir 15" dia., bears N.44¼°W., 17 lks. dist., mkd. T21S R4W S15 BT.

Reset the iron pipe and set a 6 ft. fiberglass post alongside the iron post.

Cor. Fd. and used in BLM Resurvey by Lester E. Fischer, Cadastral Surveyor, Under Group #1130, Surveyed Nov./Dec. 1982 - (DCSO records Vol. 46 Page(s) 17607-08)

Fd. OK, Oct. 1990 - M 110-72

Fd. OK by H. Christensen, Oct. 2003 - M143-28