

TOWNSHIP 21 RANGE 05 POINT IDENTIFIER # 240100

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Sec. 32; and 5 of T22-5

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GLO survey by Gordon and Gardner, under Contract #52 dated Feb. 17, 1855 (DCSO records Vol. 2 Page(s) 793)

Set ¼ sec. post, from which
A Fir 36" dia., bears N.58°E., 36 lks. dist.
A Laurel 10" dia., bears S.42°E., 41 lks. dist.

O.F. Thiel - For: Kent and Bridges and Rhodes - March 1899 -Vol. 2 Page 75 and recorded also in Vol. 2 Page 261

Dead snag of original BT, standing, part of letters visible.
Set a Fir post, from which
A double Chinquapin 20" dia., bears S.11°E., 45 lks. dist.
A Fir 14" dia., bears N.14°W., 30 lks. dist.

Douglas Co. Surveyors Office - James Byron, Deputy - Crew, Milo Godfrey; Clete Putnam - Aug. 19, 1959 - C.S. File 49/59

Found - No original BTs, but both of Thiel's BTs:
20" now mostly rotted Chinquapin stump, good scribing "BT" found S.11°E., 29.7 ft.
14" now 30" Fir stump, checks bearing and distance for NW BT.

Set Brass cap at cor. mkd: County Surveyors Office

S 32 T21S
S 5 T22S R5W
1959

New BTs -38" R.Fir bears N.7°E., 19.4 ft. scribed ¼ S32 CS BT
13" R.Fir bears S.71½°E., 70.3 ft. scribed ¼ S5 CSBT
17" Laurel bears S.54½°E. 44.2 ft. scribed ¼ S5 CSBT

Fd. B.C., Aug. 1984, F. Williams, M 97-48

Survey by Donald Peel - For: Weyerhaeuser Co. - Feb. 1992 - M 114-60

CONDITION REPORT ONLY

Found - 1¼" Iron pipe with DCSO 1959 brass cap.
19" Fir, S.72½°E., 70.0 ft., closed face, BLM tag.
19" Madrone, S.55°E., 44.1 ft., face rotted, no visible scribing, BLM tag.
38" Fir BT to North now uprooted and down.

Fd. OK, Nov. 10, 1994 - M 121-24