

TOWNSHIP 21 RANGE 05 POINT IDENTIFIER # 440700

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Sec. 3; & 34, T20-5

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO Survey by Harvey Gordon, Deputy Surveyor, Under Contract #49, dated Oct. 17, 1854 - (DCSO records Vol. 2 Page(s) 784)

Set ¼ sec. post, from which
A Maple 8" dia., bears S.43°W., 21 lks. dist.
A R.Fir 6" dia., bears N.34°W., 69 lks. dist.

Douglas County Surveyors Office - Vernon "Ray" Tracy and crew July 1965 - C.S. File 54/14-3

Found - 2" sq. post and BTs as follows:
Orig. 8" now 20" Maple, S.43°W., 13.9 ft., open and shows "¼S" reverse scribe.
Orig. 6" now 16" Fir, N.34°W., 45.5 ft. down and out of place. We do not open, badly rotted.

Set Brass cap at cor. mkd: County Surveyors Office

T 20 S

¼ $\frac{S\ 34}{S\ 3}$ R5W

T 21 S

1965

New BTs- 18" D.Fir N.34°W., 35.9 ft. mkd. ¼ S34 DCS BT.
19" Maple S.43°W., 17.2 ft. mkd. ¼ S3 DCS BT.

BLM Resurvey by Floyd A. Brooks and Timothy A. Kent, Cadastral Surveyors, under Group #648, Surveyed Aug. 1967/Sept. 1971 - (DCSO records Vol. 37 Page(s) 15259)

The ¼ sec. cor., remonumented by Tracy in 1965, with an iron post, 1" dia., firmly set, projecting 8" above ground, with brass cap mkd. in 1965, from which the remains of the original bearing trees:

A root hole bears N.34°W., 69 lks. dist., bears a down and decayed Fir alongside, 16" dia., no marks visible.

A shattered Maple stump 19" dia., bears S.43°W., 21 lks. dist., with scribe marks ¼ visible in negative on overgrowth of decayed blaze.

and bearing trees mkd. by Tracy:

A Fir 16" dia., bears N.33°W., 54 lks. dist., with healed double blaze.

A shattered Maple stump 17" dia., bears S.43°W., 25 lks. dist., with scribe marks BT visible on open blaze.

and a new bearing tree

A Hemlock 8" dia., bears S.41°W., 98 lks. dist., mkd. ¼ S3 BT.

Add the marks BLM 1967 to the brass cap.

(Cont. Next Page)

TOWNSHIP 21 RANGE 05 POINT IDENTIFIER # 440700

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Sec. 3; & 34, T20-5

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

BLM Resurvey by Bryan S. Seibold, Cadastral Surveyor, under Group #1564, Surveyed Aug/Nov. 1990 - (DCSO records Vol. 50 Page(s) 19059-60)

The ¼ sec. cor., monumented with an iron post 1¼" dia., firmly set, projecting 13" above ground, with brass cap mkd. in 1965 and BLM 1967
from which the remains of a bearing tree mkd. by Tracy, 1965
A Fir snag 20" dia., bears N.32°W., 53½ lks. dist. with fragmentary scribe marks visible on partially healed double blaze. (Rec. N.33°W., 54 lks.)
and the remains of a bearing tree mkd. by Brooks & Kent:
A Hemlock snag 12" dia., bears S.41°W., 98 lks. dist., with fragmentary scribe marks visible on partially healed blaze.
and a bearing tree of which I have no record:
A Fir 17" dia., bears S.41½°W., 97 lks. dist., with scribe marks ¼ S3 visible on opened blaze.
and a new bearing tree:
A Fir 14" dia., bears N.15°W., 55 lks. dist., mkd. ¼ S34 BT.

From this point, the BLM Geodetic Control Station No. EC 41071, at latitude 43° 46' 43.197" N., longitude 123° 16' 23.402" W. (NAD 1927), determined by the NAVSTAR Global Positioning System, bears S.62°39'26"E., 15.802 chs. dist., monumented with an alum. rod, 3/4" dia., firmly set in concrete, projecting 3" above ground, with alum. cap mkd. EC41071 GPS 1990.

Note this is on the Douglas & Lane Co. line - check with Lane Co for more corner information.