

PRIMARY CORNER DESCRIPTION Center 1/4 Cor. Sec. 25

Alias	Description

BLM dependent resurvey by Wayne Rogers & Bryan Seibold Cadastral Surveyors & Robert Browning, Surveying Technician, under Group #1814, surveyed Aug. 1996/April 1998 - (DCSO rec. Vol. 53 Page(s) 20426-7)

Point for the center ¼ sec. cor. of sec. 25, at intersection with the S. and W. center line.
Set a stainless steel post, 28" long, 2½" diam., 26" in the ground, with brass cap mkd.

T 21 S R 5 W
C ¼ S 25
1997

from which

A fir, 11" diam., bears S.3½°W., 32 lks., mkd. C¼ S25 BT.

A fir, 6" diam., bears N.59°W., 34 lks., mkd. C¼ S25 BT.

Deposit a magnet in a white plastic case at the base of the stainless steel post.

From this point, a point erroneously established as the center ¼ sec. cor. of sec. 25 by Gerald D. Riley, Registered Professional Land Surveyor No. 705, in 1994, preliminary file located at the Douglas County Surveyors Office, map file P-94 (C.S. 65/41-8), bears S.14°04'36"W., 0.100 chs., monumented with an iron rod, 5/8" diam., firmly set, projecting 7" above ground, with

red plastic cap mkd. RILEY PLS 705, from which bearing trees mkd. by Riley

A fir, 13" diam., bears N.76¼°E., 30 lks., with scribe marks C¼ S25 BT visible on open blaze.

A fir, 9" diam., bears S.12°E., 39½ lks., with fragmentary scribe marks visible on partially healed blaze.

A fir, 7" diam., bears S.19¼°W., 34 lks., with fragmentary scribe marks visible on partially healed blaze.

A fir, 9" diam., bears N.74½°W., 28 lks., with fragmentary scribe marks visible on partially healed blaze.

This point was rejected due to improper control and was not used in this survey.