

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 2 & 3

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO survey by Wm. P. Wright, Deputy Surveyor, under contract #514, dated Aug. 27, 1884 - (DCSO records Vol. 2 Page(s) 716)

Set post, 4" dia., 4 ft. long, with marked stone, 12" in ground, for qr. sec. cor. marked ¼ S on W face; from which
Fir, 24" dia., bears S.55°E., 16 lks., mkd: ¼ S BT.
Fir, 20" dia., bears S.67°W., 14 lks., mkd: ¼ S BT.

Douglas Co. Surveyors Office - Milo E. Godfrey, Deputy Co. Surveyor - V.Tracy - C.Putnam - 12/1961 - C.S. File 49/143-21

Found - 44" fir stump S.55°E., 10.6 ft. opened scar & found fragment of scribing, bottom of scar is almost at top of stump.

36" fir S.67°W. 9.2 ft. (to face) shows good scar at bottom. Tree has been rescribed (in bark) "¼SBT".
Blaze & rescribe this tree (one scar) "¼S" 3 CS BT" dist. to center of tree 10.5 ft. Bearing OK.

Set - Brass cap at corner marked:

County Surveyors Office, 1961

T21S R6W ¼ S3|S2

New BTs- 6" Hemlock N.52½°E., 24.7 ft. mkd: ¼ S2 CS BT.

Douglas Co. Surveyors Office - Larry E. Monrean & Pete Earle - 10/30/1975 - C.S. File 57/36-25

Found - 1961 CS Brass cap properly stamped.

44" now 39" Fir stump bears S.49½°E., 11.0 ft. (rec. S.55°E., 10.6 ft.) stump is rotted, has bottom of blaze no scribing.

36" now 33" fir stump bears S.67°W., 10.6 ft. (rec. 9.2 ft.) shows good scar nearly healed over, portion of scribing visible, stump has been capped with alum. sheeting, bark has been removed & a preservative applied to wood.

6" now approx. 14" hemlock stump bears N.52½°E., 24.3 ft. to face (rec. 24.1) Shows good blaze, scribed "S2 CS BT" visible, stump has been shattered & in poor condition.

New BTs- 21½" dia., Maple S.3½°E., 173.5 ft. scribed "¼ S2 CS BT"

Note - Corner lies on easterly slope, approx. S.25°E., & 200 yds from end of BLM road No. 21-6-3.1 off Blind Creek Rd. Corner lies approx. 200 ft. West of creek bottom & approx. 400 ft. East of deep saddle on ridge top. Maple bearing tree is on south edge of recently cleared area.

TOWNSHIP 21 RANGE 06 POINT IDENTIFIER # 500640

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 2 & 3

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

BLM Dependent resurvey by Wayne Rogers, Cadastral Surveyors, under Group #1231, surveyed Sept. 1984/May 1985 - (DCSO records Vol. 47 Page(s) 18056-7)

The ¼ sec. cor. of secs. 2 & 3, perpetuated & recorded by Godfrey in 1961 & Monrean in 1975, monumented with an iron post, 1¼" dia., firmly set, projecting 8" above ground with brass cap (properly) marked.

from which the remains of the orig. BTs

A sawed Fir stump, 39" dia., bears S.49½°E., 16 lks., no marks visible. (Rec. S.55°E.)

A sawed Fir stump, 33" dia., bears S.67°W., 14 lks., with fragmentary scribe marks visible on partially healed blaze.

and the remains of a BT mkd. by Godfrey

A sawed Hemlock stump, 14" dia., bears N.52½°E., 37 lks., with fragmentary scribe marks visible on decayed blaze.

and a BT mkd. by Monrean

A Maple, 29" dia., bears S.3½°E., 263 lks., with healed blaze.

and a new BT

A Fir, 4" dia., bears S.41½°W., 39 lks., mkd: X BT.

Fd. Ok by L. Roberts, 12/1992 - M116-43 & C.S. File 63/149-3H