

PRIMARY CORNER DESCRIPTION So. 1/4 Cor. for Sec. 31 only

Alias	Description
Alias	Description
Alias	Description
Alias	Description

GLO resurvey by Norman D. Price, Cadastral Engineer and Geo. Rigby, Assoc. Cadastral Engineer, under Group #282, surveyed May/Aug. 1945 (DCSO records Vol. 27 Page(s) 11374-75)

Proportional measurement.
Set an iron post 3 ft. long, 1" dia., 28" in the ground, for ¼ sec. cor. of sec. 31 only, with brass cap mkd: ¼ S 31
1945

from which
A Fir 38" dia., bears N.30°E., 227 lks. dist. mkd. ¼ S31 BT.
A Fir 34" dia., bears N.77½°E., 38 lks. dist. mkd. ¼ S31 BT.

BLM remonumentation by Floyd A. Brooks and James E. Jelley, Cadastral Surveyors, under Group #'s 514 and 350, surveyed June 1963/March 1965 (DCSO records Vol. 33 Page(s) 13731)

The ¼ sec. cor. of sec. 31 only, the iron post set by Price is found leaning and partially covered by a fallen tree; the true position is determined from the original bearing trees:
A Fir stub 38" dia., bears N.30°E., 227 lks. dist. with scribe marks ¼ S visible on partially healed blaze.
A Fir 35" dia., bears N.77½°E., 38 lks. dist. with a burned out blaze.

At the corner point
Reset the iron post 3 ft. long, 1" dia., 30" in the ground, with brass cap marked: ¼ S 31
1945

from which a new bearing tree,
A Fir 56" dia., bears N.69½°W., 203 lks. dist. mkd. ¼ S31 BT.

Douglas Co. Surveyors Office - Milo E. Godfrey, Deputy - Mike Stone & Wm. Stoffel, crew - Sept. 1963 - C.S. File 52/14

Found - Brass cap set by Cadastral survey in 1945.
Stump of 38" Fir N.30°E., 149.8 ft.
34" Fir N.77½°E., 25.1 ft., no scribing visible, old face badly burned. Blaze and rescribe "¼ S31 CS BT"
60" Fir N.72°W., 134.0 ft., recently blazed and scribed ¼ S31 BT.