

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 21 & 22

Alias	Description
_____	_____
_____	_____
_____	_____
_____	_____

GLO survey by Alonzo Gesner, Deputy Surveyor, under Contract #608, dated April 17, 1893 - (DCSO rec. Vol. 2 Page(s) 945)

-----  
Set Cedar post, 4½ ft. long, 4" sq., 24" in the ground on hillside sloping NE, for ¼ sec. cor., mkd: ¼ S on W face; from which

- A Cedar, 8" dia., bears N.71°30'E., 26 lks., mkd: ¼ S BT.
- A Fir, 16" dia., bears N.10°W., 40 lks., mkd: ¼ S BT.

Les Roberts - For: International Paper Co. - March 10, 1983 - M94-4

- 
- Found - 24" Cedar stub, N.79°E., 17.2 ft. (no marks) 1894 BT  
42" Cedar line tree, North 31.7 ft. no marks.  
16" downed Fir N.10°W., 26.4 ft. (cut open & found scribing "¼ S". 1894
- Set - 1½" x 36" iron pipe & brass cap stamped with S-T-R, date & PLS No. 1039  
29" Hemlock, N.70°E., 47.6 ft. scribed/set washer.  
56" Cedar, S.6°W., 12.2 ft. scribed/set washer.

Fd. & used on BLM dependent resurvey by John A. Farmer, Cadastral Surveyor, under Group #1399, surveyed Aug./Sept. 1987 - (DCSO records Vol. 48 Page(s) 18457)

Douglas Co. Surveyors Office - Randall W. Smith, Deputy - Stephen J. Flause - John Pike - May 20, 1992 - C.S. File 64/26-11

- 
- Found - 2½" dia., brass cap marked "T20S R9W ¼ 21|22 1983 PLS 1039 (mis-marked) on a 1½" OD iron pipe, firmly set & protrudes approx. 3" above ground. A ½" dia., 36" long steel rebar post with a yellow boundary sign is loosely set at north edge of found brass cap. Sign & post were temporarily removed from monument vicinity to relieve magnetic influence on compass bearings. 1983
- 8" Cedar now a 2½" tall by 24" dia. rotted stump with no scribing visible bears N.79°E., 17.2 ft. (rec. N.71½°E., 17.2 ft.) OBT
- 16" Fir now a fallen & rotted 18" dia., fir with a previously opened blaze showing the scribing "¼ S". The base & root hole of which bears N.10°W., 26.4 ft. (as per record)

Evidence of an orig. line tree is also found.  
continued next page

TOWNSHIP 21 RANGE 09 POINT IDENTIFIER # 400340

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 21 & 22

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

48" Cedar now a rotted & broken 42" D.B.H. by 20 ft. tall cedar snag with 2 notches on the north edge and 3 notches on the south edge of its trunk, bears North 31.7 ft. (as per rec.)  
Evidence of two BTs from 1983  
29" Hemlock now a 31" dia., 5 ft. tall stump with a partially healed double blaze revealing the scribing "¼ S22 BT" w/brass washer bears N.68¼°E., 47.6 ft. (rec. N.70°E., 47.6 ft.)  
56" Cedar now a 58" D.B.H. with a partially healed double blaze revealing the scribing "E ¼ S21" w/brass washer bears South 12.2 ft. (rec. S.6°W., 12.2 ft. bearing to brass washer is S.4°E.)  
Set - Township designation on found brass cap should read T21S not T20S. Brass cap markings were corrected in field.  
8" dia., D.B.H. Hemlock double blazed & scribed "¼S S22 CS BT" bears S.86°E., 32.4 ft.  
Rebar & attached sign are returned to position at N edge of monument.  
Note - Monument is on a north south cutting line on steep NNE slope. Monument is approx. 500 ft. westerly from a logging rd. running in a northerly direction.