

PRIMARY CORNER DESCRIPTION 1/4 Cor. Sec., 22 only

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO survey by William Thiel under contract 342 dated Oct. 6, 1879 - (DCSO records Vol. 3 Page(s) 1017)

Set for ¼ Sec. post a rock, 24"x24x16 in middle of rocky canyon, above the forks of two canyons, from which:

A Fir, 24" dia., bears S.76°E., 62 lks.

A Chittewood, 3" dia., bears West 3 lks.

GLO resurvey by Fred Mensch, Charles M. Collier and Fred W. Rodolf, U.S. Cadastral Engineers; Elmer F. Strickler, U.S. Surveyor, and Gerald A. Sorrels, U.S. Transitman, under Instructions dated April 24, 1917 (surveyed 1919) - (DCSO records Vol. 3 Page(s) 1087-8)

Intersect point for old ¼ sec. cor. located by reference to the old SE BT. The old cor. stone has been forced down hill by the action of a falling tree. I change this cor. to refer to Sec. 22 & at the exact cor. point set an iron post, 3 ft. long, 1" dia., 26" in the ground, for ¼ Sec. cor. of sec. 22 only, with brass cap mkd:

¼
S 22|
1919

from which

A Chittewood, 6" dia., bears S.66°W., 7 lks., mkd: ¼ S22 BT.

A Chittewood, 8" dia., bears N.4°W., 23 lks., mkd: ¼ S22 BT.

Herman A. Pieske, RLS #1651 - For: Siuslaw National Forest USDA - Dec. 1983 - M 95-80 A & B

Found - 2" pipe filled with concrete badly rusted. Brass cap broken off and gone. (1919)
64" D.Fir bears S.76°E., 40.9 ft., healed face.
10" Chittewood, blown down, bears S.87°E. 5.0 ft ± rotted face.

Set - At location of broken pipe, set 2½" x 30" alum. pipe, 26" in the ground, with 3" alum. cap mkd:
"US Dep of Agri-Forest Service T21S R10W ¼ S22 RLS 1651 1983 Unlawful to Disturb.
10" Hemlock bears S.40°W., 23.8 ft., faced & scribed: ¼ S22 BT.