

TOWNSHIP 21 RANGE 10 POINT IDENTIFIER # 600700

PRIMARY CORNER DESCRIPTION Sec. Cor. for 1 & 2 only, (North)

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GL0 resurvey by Fred Mensch, Charles M. Collier and Fred W. Rodolf, U.S. Cadastral Engineers; Elmer F. Strickler, U.S. Surveyor, and Gerald A. Sorrels, U.S. Transitman, under Instructions dated April 24, 1917 (Group #36) (surveyed 1919) - (DCSO records Vol. 1 Page(s) 259)

Set an iron post 3 ft. long, 2" dia., 24" in the ground for cor. of secs. 1 and 2, with brass cap mkd:

S2	S1
T21S	R10W
1919	

from which

A Hemlock 10" dia., bears S.53°E., 25 lks. dist. mkd. T21S R10W S1 BT.

A Hemlock 28" dia., bears S.55°W., 22 lks. dist. mkd. T21S R10W S2 BT.

BLM resurvey by Thomas A. Tillman, Cadastral Surveyor, under Group #297, Surveyed May 1951/Oct. 1952 - (DCSO records Vol. 27 Page(s) 11666)

The cor. of secs. 1 & 2, monumented with an iron post 2" dia., 8" above ground, firmly set, with brass cap mkd. in 1919, from which the 1919 bearing trees:

A rotted Hemlock stump 10" dia., bears S.53°E., 23 lks. dist. with traces of scribe marks visible on decayed blaze on fallen trunk. (Rec. dist. 15 lks.)

A Hemlock 26" dia., bears S.58½°W., 21 lks. dist. with partial scribe marks visible on unhealed portion of blaze. (Rec. description, S.55°W., 22 lks. dist.)

The old iron post is rusted nearly through; in its place Set an iron post 3 ft. long, 2" dia., 28" in the ground with brass cap mkd.

T 20 S R 10 W	
S 36	
S 2	S 1
T 21 S R 10 W	
1951	

from which a new bearing tree:

A Hemlock 22" dia., bears S.42°45'E., 35 lks. dist. mkd. T21S R10W S1 BT.

Deposit the old iron post at the base of the new iron post.

Douglas Co. Surveyors Office - Gary Langlitz; Clell Goodwin; Vic Cangie; Lenora Ladig - Nov. 12, 1975 - C.S. File 57/39-7

Found - US GL0 brass cap leaning to South after apparent bulldozer damage. Cap properly marked.

(Cont. Next Page)

TOWNSHIP 21 RANGE 10 POINT IDENTIFIER # 600700

PRIMARY CORNER DESCRIPTION Sec. Cor. for 1 & 2 only, (North)

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

Found - No identifiable trace of the SE. 1919 BT.
The rotting remains of the SW. 1919 BT is in its record position with reference to the 1951 resurvey. This tree is now down and any identifying marks are buried.
The SE. BT mkd. in 1951 is down, bearing S.42 3/4°E., 23.1 ft. with scribing visible on an unhealed blaze.
We RESET the brass cap and the remains of the 1919 Iron post in the proper position and add the following markings to the brass cap. "CS 1975".
New BTs- A 28" Hemlock bears S.53°E., 41.7 ft. scribed "T21SR10W S1 CS BT" on a double blaze.
A 17" D.Fir bears S.22°W., 35.2 ft. scribed "T21SR10W S2 CS BT" on a double blaze.
The SW. cor. Sec. 36, T20SR10W, bears N.89°15'W., 86.5 ft. This cor. is located on a ridgetop near the SW. corner of a clearcut unit.

Jerry Estabrook - For: Roseburg Resources - 1/2022 - M180-48

Found - A 2" iron pipe with 2½" brass cap (properly) marked Set steel post alongside.
A 28" Hemlock with no visible marks bears S.53°E., 41.7'.
A 17" Fir stump with healed face bears S.2°W., 35.2'
New BTs- A 15" Hemlock, face scribed "NW S1 BT" with X-chop and tag bears S.82°E., 15.1' to a spike at side center.
A 13" Hemlock, face scribed "NW S1 BT" with X-chop and tag bears S.32°E., 17.1' to a spike at side center.
A 9" Hemlock, face scribed "X BT" with X-chop and tag bears N.85°W., 9.7' to a spike at side center.
An 11" Hemlock, face scribed "X BT" with X-chop and tag bears N.48°W., 25.2' to a spike at side center.
Lat and Long per GARMIN ETREX hand held GPS.
N: 43°46'57.4" W: 123°50'56.9"