

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 1 & 12

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO resurvey by Fred Mensch, Charles M. Collier and Fred W. Rodolf, U.S. Cadastral Engineers; Elmer F. Strickler, U.S. Surveyor, and Gerald A. Sorrels, U.S. Transitman, under Instructions dated April 24, 1917 (surveyed 1919) - (DCSO records Vol. 3 Page(s) 1081-2)

Set an iron post, 3 ft. long, 1" dia., 26" in the ground, for 1/4 Sec. cor., with brass cap mkd:

1/4 $\frac{S \ 1}{S \ 12}$
1919

from which

A Fir, 30" dia., bears N.11°E., 39 lks., mkd: 1/4 S1 BT.

A Cedar, 18" dia., bears S.80°W., 30 lks., mkd: 1/4 S12 BT.

BLM rehabilitation of a corner by Peter A. Peterson, Cadastral Surveyor, under group #350, surveyed May 12, 1967 - (DCSO records Vol. 35 Page(s) 14601)

The 1/4 sec. cor. of secs. 1 & 12, monumented with an iron post, 1" dia., firmly set protruding 10" above the ground, with brass cap properly marked, from which the orig. BTs:

A stump hole, bears N.11°E., 39 lks., with the uprooted Fir, 32" dia., lying 50 lks. West, with illegible scribe marks visible on rotted blaze.

A Cedar, 19" dia., bears S.80°W., 30 lks., with illegible scribe marks in negative visible on over growth of rotted blaze.

and new BTs:

A Fir, 70" dia., bears N.63°E., 61 lks., mkd: 1/4 S1 BT.

A Fir, 52" dia., bears S.41°E., 114 lks., mkd: 1/4 S12 BT.

Douglas Co. Surveyors Office - Stephen J. Flause, Dep. - Karen Mosley - April 2, 1981 - C.S. File 61/19-26

Found - A properly marked 1919 US GLO brass cap on a rusted & broken 1" dia. IP which is firmly set & protruding 10" above the ground. Brass cap fell loose from the IP during the investigation of the accessories.

Orig. 30" Fir NE BT is now a nearly obliterated stump hole agreeing well in location w/orig. rec. bearing & dist.

Orig. 18" now a 20" DBH Cedar, bears S.80°W., 19.8 ft. & has an opened blaze w/no scribing visible.

continued next page

TOWNSHIP 21 RANGE 10 POINT IDENTIFIER # 640600

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 1 & 12

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

A Fir, 70" now a Fir stump 30" tall & 72" dia., bears N.63°E., 40.3 ft. Tree has good evidence of a blaze. 1957
A Fir, 52" now a 55" D.Fir, DBH bears S.41°E., 75.2 ft. Tree has a well healed & clearly identifiable double blaze.
Set - Fd. mon. location is accepted, referenced out & then removed. In referenced location, is placed a DCS0 2½" brass cap on a 1"x30" IP mkd: COUNTY SURVEYOR'S OFFICE T21S ¼ S1 S12 R10W 1981. New cap is firmly set and protrudes 9" above ground.
10" DBH Hemlock bears S.62½°E., 28.1 ft. and is scribed ¼ S12 CS BT on a double blaze. Tree also has an injury scar approx. 12" long & 36" above the ground on its north face.
All trees are tagged with DCS0 BT tag.

Jerry Estabrook - For: Roseburg Resources - 1/2022 - M180-48

FOUND - A 1" iron rod with 2½" brass cap (properly) marked
Set steel post alongside
A Original 32" cedar with healed face bears S.80°W., 19.8'. Placed new tag on BT.
A 72" Fir stump with healed face and tag bears N.63°E., 40.3'.
A 22" Hemlock with healed face bears S.62°30'E., 28.1'. Placed new tag on BT.
New BTs- A 15" Alder, bark scribed "S¼ S1 BT" with X-chop and tag bears N.38°E., 25.6' to a spike at side center
A 9" Alder, bark scribed "S¼ S1 BT" with X-chop and tag bears N.19°W., 15.7' to a spike at side center.
Lat and Long per GARMIN ETREX hand held GPS:
N: 43°46'09.4" W: 123°50'20.3"