

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 4 and 5

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO survey by Wm. Thiel, Deputy Surveyor, under Contract #567, dated Feb. 16, 1891 (DCSO records Vol. 3 Page(s) 1245)

Set a post 5 ft. long, 3" sq., 24" in the ground, for 1/4 sec. cor. marked 1/4 S on W. face, from which

A Cedar 16" dia., bears S.60°E., 18 lks. dist. mkd. 1/4 S BT
A Hemlock 10" dia., bears N.59°W., 13 lks. mkd. 1/4 S BT.

Douglas Co. Surveyors Office - Vernon "Ray" Tracy, Jack Heritage, E. West, crew - March 1967 - C.S. File 54/1-36

Found - 3/4" I.P. with 1 1/2" x 4 ft. I.P., 36" above ground. Orig. 24" Cedar stump S.88°E., 9.6 ft. (Rec. S.60°E., 11.9 ft.), shows old line blaze on South side. We open 55 years, no scribe.

No trace of any other BTs.

R.E. Keiner found this pipe in 1947 and stumps of old BTs with burned faces. Call on creek fits real good.

Set Brass cap at cor. mkd: County Surveyors Office
T 21 S R 11 W
1/4 S 5 | S 4
1967

Reset iron pipe alongside.

New BTs -12" Alder S.75°E., 39.1 ft. mkd. 1/4 S4 CS BT.

19" Alder S.18°W., 50.3 ft. mkd. 1/4 S5 CS BT.

This corner lies 66 ft. N. of creek, course SW.

Douglas County Surveyors Office - Gary L. Langlitz; P.L. Earle, crew - Jan. 18, 1977 - C.S. File 59/29-13

Found - 1967 DCSO brass cap, firmly set, on a SE slope, extending 12" out of ground, properly marked.

Remains of a 3/4" I.P. badly rusted, firmly set at the base of the brass cap.

We find the rotting remains of a 24" Cedar stump, S.88°E., 9.6 ft. as described by Tracy, however we do not identify it as an orig. BT.

We find no evidence of the orig. NW BT.

A 1967 BT, a 12" now 16" Red Alder, alive with scribing "1/4 S" visible on partially healed blaze, bears S.75°E., 39.1 ft.

A 1967 BT, a 19" now 22" Red Alder, alive with scribing "1/4" visible on partially healed blaze bears S.18°W., 50.3 ft.

New BT - 24" D.Fir bears S.30°E., 119.7 ft. scribed "1/4 S4 CS BT" on a double blaze.