

TOWNSHIP 22 RANGE 04 POINT IDENTIFIER # 300600

PRIMARY CORNER DESCRIPTION Sec. Cor. for 4, 5, 8 and 9

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GL0 survey by Harvey Gordon and Charles T. Gardner, Deputy Surveyors, under Contract #52 dated Feb. 17, 1855 (DCSO records Vol. 3 Page(s) 1343)

Set post cor. of secs. 4, 5, 8 and 9, from which
A Fir 40" dia., bears N.37°E., 72 lks. dist.
A Fir 21" dia., bears N.48°W., 64 lks. dist.
A Fir 50" dia., bears S.81°W., 47 lks. dist.
A Fir 4" dia., bears S.50°E., 95 lks. dist.

GL0 survey by WP Wright, U.S. Deputy Surveyor, under Contract #514, dated August 27, 1884 (DCSO records Vol. 4 Page 1364)

Place for cor., but the trees and post are too badly deface. Set post 6" dia., 4 ft. long, with marked stone, 12" in ground for cor. to secs. 8,9, 4 and 5, mkd. T22S S4 on NE.; R4W S9 on SE.; S8 on SW.; S5 on NW. face with 4 notches on E. and 5 on S. edge, from which
A Fir 4" dia., bears N.48°W., 64 lks. mkd. T22S R4W S5 BT.
A Fir 6" dia., bears N.37°E., 72 lks. mkd. T22S R4W S4 BT.
A Fir 8" dia., bears S.50°E., 95 lks. mkd. T22S R4W S9 BT.
A Fir 5" dia., bears S.81°W., 47 lks. mkd. T22S R4W S8 BT.

Kenneth P. McReynolds, LS #277 - Feb. 1955 - C.S. File 41/340

BT. OK. Stake badly rotted.
Set Iron rod 5/8" x 26" in its place.

Douglas County Surveyors Office - James W. Byron, Deputy - M. Godfrey; S. Bilow, crew - May 12, 1958 - C.S. File 49/59-22

Found - 3/4" I.P. at corner.
Orig. 21" now 26" R.Fir, has open face, good scribing.
Now 60" Fir that checks bearing and distance for orig. SW BT, has old axed face, for bark scribing and I find faint line.
No trace of SE BT.
Find 60" stump that checks bearing. & distance for NE orig. BT.
New BTs -18" W.Fir bears S.50°E., 22.1 ft. scribed S9 T22S R4W CS BT.
16" W.Fir bears N.35°E., 59.0 ft. scribed S4 T22S R4W CS BT.
60" R.Fir bears S.80°W., 35.0 ft. bark scribed S8 T22S R4W CS BT.
I rescribed orig. N.48°W., 42.2 ft. BT, S5 T22S R4W CS BT.

Cont.

TOWNSHIP 22 RANGE 04 POINT IDENTIFIER # 300600

PRIMARY CORNER DESCRIPTION Sec. Cor. for 4, 5, 8 and 9

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

Glen McChesney - For: Weyerhaeuser Co. - June 9, 1959 - C.S.
File 53/105-2

Added Plates and "W" nails to County BTs.

BLM resurvey by Donald Beck, Cadastral Surveyor, under Group #516
-Surveyed July 29/Aug 23, 1963 - (DCSO recs Vol. 32 Pg 13430)

The Sec. cor., remonumented with a wood post, 4 ft. long, 4" sq., firmly set 12" in the ground, mkd. with a scribe S4 S5 S8 S9, from which the remains of the original bearing trees:

A sawed Fir stump 60" dia., bears N.38°E., 72 lks. dist., no marks remaining. (Rec. bearing N.37°E.)

A Fir snag 67" dia., bears S.80°W., 50 lks. dist. to face, no original marks remaining on old bark blaze, re-marked by County Surveyor T22S R4W S8 CS BT on bark blaze. (Rec. brg. S.81°W., 47 lks. dist.)

A Fir 27" dia., bears N.46½°W., 64 lks. dist. with illegible scribe marks on bark blaze, re-marked by County T22S R4W S5 CS BT on double blaze.

and bearing trees mkd. by the County Surveyor:

A Fir 18" dia., bears N.34 3/4°E., 91 lks. dist. mkd. with a healed double blaze.

A Fir 21" dia., bears S.51 3/4°E., 32½ lks. dist. mkd. with a healed double blaze.

At the corner point

Set an iron post, 28" long, 2 1/2" dia., 22" in the ground, with brass cap mkd:

T 22 S R 4 W
S 5 | S 4
S 8 | S 9
1963

from which a new bearing tree:

A Fir 12" dia., bears S.68¼°W., 64 lks mkd. T22S R4W S8 BT
Reset the wood post alongside the iron post.

Fd. OK, Feb. 1991 - M 111-75

Fd. OK, Sept. 1992 by D. Peel - M 115-77

BLM Dependent resurvey by A Bert Skeesick Cadastral Surveyor, and Robert H. Browning, Surveying Tech. Group No. 2170 surveyed Aug 2007/Feb 2008 - (DCSO recs Vol. 55 Pg 21813-4)

The cor. of secs. 4, 5, 8, & 9, monumented with an iron post, 2½" dia., loosely set and leaning, projecting 18" above ground (alongside of which is an iron pipe, 25" long, 3/4" dia.), with brass cap mkd.

from which the remains of original bearing trees

continued next page

TOWNSHIP 22 RANGE 04 POINT IDENTIFIER # 300600

PRIMARY CORNER DESCRIPTION Sec. Cor. for 4, 5, 8 and 9

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

A sawed, decayed fir stump, 62" dia., bears N.38°E., 47.5 ft., no marks visible.
A decayed fir root crown bears S.80°W., 33.0 ft., with fallen fir trunk, 72" dia., lying alongside, no marks visible.
A fir, 47" dia., bears N.46½°W., 42.2 ft., with a healed blaze.
and the remains of BTs mkd. by Byron, in 1958, reported by Beck
A root hole, bears N.34¾°E., 60.1 ft., with fallen fir trunk, 32" dia., lying alongside, no marks visible.
A fir, 38" dia., bears S.51¾°E., 21.4 ft., with a healed blaze.
At the cor. point
Reset the iron post, 28" long, 2½" dia., 24" in the ground, from which new bearing trees
A fir, 24" dia., bears N.10¾°E., 66.0 ft., mkd. T22S R4W S4 BT.
A fir, 13" dia., bears S.36¾°W., 35.6 ft., mkd. T22S R4W S8 BT.
Deposit the iron pipe inside the iron post.