

PRIMARY CORNER DESCRIPTION Sec Cor for 2, 3, 10 and 11

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GL0 survey by W. P. Wright, U.S. Deputy Surveyor, under Contract #514, dated August 27, 1884 (DCSO records Vol. 4 Page(s) 1422-23)

Set post 6" dia., 4 ft. long with marked stone 12" in ground for cor. to secs. 2, 3, 10 and 11 mkd: T22S S2 on NE.; R5W S11 on SE.; S10 on SW.; S3 on NW. face, with 2 notches in E. and 5 in S. edges; from which
A Fir 12" dia., bears N.64°W., 4 lks. dist., mkd. T22S R5W S3 BT.
A Cedar 48" dia., bears N.78°E., 26 lks. dist., mkd. T22S R5W S2 BT.
A Fir 12" dia., bears S.9°E., 54 lks. dist. mkd. T22S R5W S11 BT.
A Fir 40" dia., bears S.8°W., 103 lks. dist. mkd. T22S R5W S10 BT.

B.H. McGillicuddy - For: Whipple Lumber Co. - April 1952 - RM 1-40

New post and Iron pipe, 5.0 ft. West of fence corner.
Original BTs:
48" Cedar N.78°E., 26 lks., now stump.
All other bearing trees destroyed.

Douglas Co. Surveyors Office - James Byron, Deputy - Crew, Milo Godfrey; A. Bilow - Jan. 31, 1958 - C.S. File 49/59-5

Found - Orig. 48" now 60" Cedar stump shows old face and faint scribing "T R /", N.78°E., 17.2 ft.
Bases of orig. SW and NW BTs., check brg. and dist. ½" I.P. and 3" x 3" sq. scribed stake at corner.
Set Brass cap at cor. mkd: County Surveyors Office
T 22 S R 5 W
S 3 | S 2
S 10 | S 11
1958
New BTs -10" R.Fir N.34°E., 39.5 ft. scribed S2 T22S R5W CSBT
11" R.Fir N.13°W., 21.2 ft. scribed S3 T22S R5W CSBT
6" R.Fir S.61½°E., 120.8 ft. scribed S11 T22S R5W CS BT.
8" R.Fir S.8°W., 54.2 ft. scribed S10 T22S R5W CS BT

Douglas Co. Surveyors Office - Larry E. Monrean, Deputy - S.J. Flause, crew - Nov. 20, 1990 - C.S. File 64/11-2

(Cont. Next Page)

TOWNSHIP 22 RANGE 05 POINT IDENTIFIER # 500600

PRIMARY CORNER DESCRIPTION Sec Cor for 2, 3, 10 and 11

Alias	Description
_____	_____
Alias	Description
_____	_____
Alias	Description
_____	_____
Alias	Description
_____	_____

Found - 1958 DCSO brass cap 2 3/8" dia. on a 1 3/8" dia. galv. I.P. 60" Cedar stump with fragmentary scribing bears N.78°E., 17.2 ft. to face. Orig. BT. 40" Fir stump no scribing visible, bears S.8°W., 68.0 ft. Orig. BT. 20" now 26" Fir stump 4½ ft. high with well healed double blaze bears N.34°E., 39.5 ft. 16" now 28" Fir with well healed double blaze bears N.13°W., 21.2 ft. 18" now 24" Fir with healed blaze bears S.3°W., (Rec. S.8°W., 53.4 ft.) 18" now 30" Fir stump 1½ ft. high bears S.65¼°E., (Rec. S.60½°E) 120.8 ft. New BT - 9" D.Fir double blazed and scribed "S11 CS BT" bears S.53½°E., 61.5 ft. Fences running N. and W. intersect at corner. Clear cut to East.
Fd. OK, Feb. 1991, M 111-54 Fd. OK, Sept. 1993, D.Baker, M 118-10
Rex Betz - For: W.E. McArthur & Assoc. - 3/15/1999 - M 131-27 ----- Condition report only Found - 2½" DCSO brass cap in East - West fence with BTs per DCSO's map M49-12. Note - The 16" D.Fir BT bearing N.13°W., 21.2 ft. is no longer standing a neighbor reported that it had blown over in a wind storm.
Found OK by T. Rambo, Jan. 2004 - M143-75
DCSO-GIS Corner visitation - 10/11/2005 - Typed: 1/18/2011 - C.S. File 67/33-1 ----- Monument - 1¼" IP W/BC Comment - OK, 3 standing BTs
Douglas Co. Surveyors Office - Stephen J. Flause - Mike Koch - April 24, 2013 - C.S. File 67/38-26 ----- Found - Orig. 12" stone and 1952 iron pipe not seen (we did not disturb fd. mon. to search) A 2½" dia., brass cap (properly mkd) on a 1" I.D. iron pipe firmly and plumbly set protruding approx. 9" above ground.
continued next page

PRIMARY CORNER DESCRIPTION Sec Cor for 2, 3, 10 and 11

Alias	Description
Alias	Description
Alias	Description
Alias	Description

A cedar 48" dia., now a 57" dia., 7 ft. tall cedar stump with no blazes or marks visible; bears N.72°E., 18.6 ft. (orig. dist. of 17.2 ft. would be a good orig. face measurement) (orig.)

A 10" R.Fir now a 29" dia., 4 ft. tall fir stump with a fully healed double blaze; bears N.31½°E., 39.5 ft. (Rec. N.34°E., 39.5 ft.) 1958

An 11" R.Fir, now a 35" dia., D.Fir with a fully healed double blaze; bears N.13°W., 21.2 ft. (as per rec). This tree was erroneously described as blown down in a 1999 condition report. This tree will be cut to a low stump soon. 1958

A 6" R.Fir, now a 30" dia., 1½ ft. tall fir stump showing some blaze healing over a rotted away face; bears S.65¼°E., 120.8 ft. (bearing agrees with 1990 meas., dist. is record) 1958

An 8" R.Fir, now a 36" dia., D.Fir with a fully healed single blaze; bears S.5½°W., 53.4 ft. (dist. agrees with 1990 rec.)

A 9" D.Fir now a 16" D.Fir with a fully healed double blaze; bears S.53½°E., 61.5 ft. (as per rec.) 1990

New - An 8" dia., D.Fir scribed "T22S R5W S10 CS" "BT" on a double blaze; bears S.27°W., 35.2 ft.

Note - Monument is on generally flat ground with a gentle slope coming down from SE in old regrowth fir forest.

Compass decl. 15½°E.