

TOWNSHIP 22 RANGE 06 POINT IDENTIFIER # 540500

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 11 and 14

Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

GLO survey by Gordon and Gardner, under Contract #52 dated Feb. 17, 1855 (DCSO records Vol. 4 Page(s) 1442)

-----  
Set ¼ sec. post, from which  
A Fir 24" dia., bears S.25°W., 39 lks. dist.  
A Fir 22" dia., bears N.45°W., 12 lks. dist.

Douglas Co. Surveyors Office - Milo E. Godfrey, Deputy - V. Tracy & C. Putnam, crew - Nov. 29, 1961 - C.S. File 49/143-94

-----  
Corner Report Only  
From tie shown on Map of Hwy. #38, Found 1" pipe in N. and S. fence line. No evidence (except tie on Hwy. #38) found to indicate that it is ¼ cor. Old stumps near pipe do not fit original calls for BTs.

Survey by James A. Branch, LS #1138 - For: U.S. National Bank of Oregon - March 1990 - C.S. File 63/104-12 and M 109-74 A&B

-----  
No evidence of original corner was found. A thorough search was also made for the I.P. that W. Haines called the corner in DCSO files, M 18-32. No evidence of the pipe was found. Based on other monuments found that were set in his survey, we calculated the approx. position of the pipe to be N.22°31'E., 13.5 ft. from the corner set. Unable to determine the origin of the pipe and did not hold to its calculated position. Corner was reestablished by proportionate measurement, on line at the midpoint between the SW sec. cor. and the SE sec. cor. of sec. 11.

Set 5/8" x 30" rebar with yellow plastic cap mkd. "Branch Eng LS1138".

Blazed and scribed bearing trees as follows:

- 10" D.Fir scribed "S¼ S11 BT" bears N.54°30'W., 78.5 ft.
- 6" W.Oak scribed "S¼ S11 BT" bears N.47°15'E., 20.5 ft.
- 11" W.Oak scribed "N¼ S14 BT" bears S.83°15'E., 18.0 ft.
- 12" W.Oak scribed "N¼ S14 BT" bears S.45°15'W., 134.4 ft.