

TOWNSHIP 22 RANGE 06 POINT IDENTIFIER # 640600

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 1 and 12

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GLO survey by Gordon and Gardner, under Contract #52 dated Feb. 17, 1855 (DCSO records Vol. 4 Page(s) 1438)

Set ¼ sec. post, from which
 A B.Oak, 15" dia., bears N.31°W., 25 lks.
 A B.Oak, 18" dia., bears S.38°W., 79 lks.

O.F. Thiel - For: Ray B. Ritchey - 1903 - C.S. File 64/48-7

... S.89½°E., from NW cor. through prairie; desc. 40.20
intersect N of ¼ 44 lks. marked new trees

Douglas Co. Surveyors Office - Milo E. Godfrey, Deputy -
1961-1962 - C.S. File 49/143-2

Corner not found.

Douglas Co. Surveyors Office - Randall W. Smith, Deputy -
Stephen J. Flause - 9/19/2001 - C.S. File 66/29-9

Preservation of possible position

Found - No orig. B.Oak BTs found.
No monuments found.
30" dia., W.Oak snag with center rotted out in an E-
W fence line this tree has been previously opened
in past on SE, NE & W of trunk snag also has old
line blazes on W & E trunk, no scribing found.
In 1903 new BTs marked at corner no brg. or dist.
given, see C.S. 64/48 pg 7.
Position of above Oak snag fits reasonably with
rough tie to stone monument set on DLC 44 line,
intersection with sec. line, 1903? See C.S. 64/48
pg. 8 (PLSS 646600)
Set - 5/8" x 30" long iron rod with yellow plastic cap is
set at center of snag to protect its position as
snag is in poor shape.