

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 1 and 2

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GLO survey by W.H. Byars, Deputy Surveyor under contract # 152 survey dated June 3, 1871 (DCSO records Vol. 4 Page(s) 1516)

Set 1/4 sec. post, from which
 A Fir 16" dia., bears East, 10 lks. dist.
 A Fir 6" dia., bears S.20°W., 15 lks. dist.

O.F. Thiel - For: Carl Binder - April 1943 - Field Book 117 Page 95

No bearing trees to be found. Set a Fir post, 5" sq. 4 ft. long.

BLM resurvey by Boyd W. Peterson, Cadastral Surveyor, under Group #1346, surveyed Sept/Dec. 1986 (DCSO records Vol. 48 Page(s) 18308-09)

Point for the 1/4 sec. cor., at proportionate distance; there is no remaining evidence of the original corner.

Set an stainless steel post, 28" long, 2 1/2" dia., 24" in the ground, with brass cap mkd:

T 22 S R 7 W

1/4

S 2*S 1

1986

from which

 A Fir 19" dia., bears S.70 1/2°E., 13 lks. dist. mkd. 1/4 S1 BT

 A Fir 25" dia., bears S.48 1/4°W., 14 lks. dist. mkd. 1/4 S2 BT

Deposit white "DEEP-1" magnetic marker at base of stainless steel post.

Ron Rice, NW Land Surveying - For: Seneca Jones Timber Co. - Oct. 2013 - C.S. File 65/79-18

Found - 3 1/4" BLM brass cap dated 1986, with the following accessories:

 27" D.Fir bears S.70 1/2°E., 8.6' healed face

 30" D.Fir bears S 48 1/2°W., 9.2', healed face

 Steel post adjacent to corner

 All accessories have red painted band and face plus bearing tree tag.