

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 20 and 29

| Alias | Description |
|-------|-------------|
| _____ | _____ |
| _____ | _____ |
| _____ | _____ |
| _____ | _____ |

BLM resurvey by Floyd Brooks and Peter Peterson, Cadastral Surveyors - under Group #'s 595 and 657 - surveyed Aug. 1965/Dec. 1967 - (DCSO recs Vol. 34 Page(s) 14116 and 14119)

(Page 14116)

(The line between secs. 20 and 29 was run in two parts, the east portion was surveyed by Gordon and Gardner in 1855-56 and the west portion was surveyed by Byars in 1881. The two portions of the line were not connected or tied together in the original survey, therefore, during this survey the west segment of the line was projected West, record bearing and distance from the cor. of secs. 20, 21, 28 and 29, and the west segment of the line was projected East, record bearing and distance from the cor. of secs. 19, 20, 29 and 30, and a tie made between the terminal points of the lines.)

(Page 14119)

Point for the 1/4 sec. cor. of secs. 20 and 29, at midpoint in departure bet. the cor. of secs. 19, 20, 29 and 30, and the cor. of secs. 20, 21, 28 and 29.

Set an iron post 28" long, 2 1/2" dia., 22" in the ground, with brass cap mkd:

$$\frac{1}{4} \begin{array}{l} S 20 \\ S 29 \end{array}$$

T 22 S R 8 W
1965

from which

A W.Oak 6" dia., bears N.15°E., 53 lks. mkd. 1/4 S20 BT.

A W.Fir 12" dia., bears S.19°W., 9 lks. mkd. 1/4 S29 BT.

Douglas Co. Surveyors Office - Stephen J. Flause - John Pike - 9/20/2005 - C.S. File 67/13-9

Found - 3" dia., brass cap (properly marked) projects 3" above ground.

Orig. 12" now 31" dia., W.Fir no blaze visible, bears S.19°W., 5.9 ft. (agrees w/rec) 1965 BT

Orig. 6" now 8" dia., x 1 1/2" ft. tall decayed W.Oak stump. No blazes visible, bears N.16 1/2°E., 35.0 (rec. N.15°E., 35.0) 1965 BT

New - 11" dia., D.Fir, double blazed & scribed "1/4 S29 CS BT" bears S.49 1/2°E., 11.0 ft.

11" dia., W.Oak, double blazed & scribed "1/4 S29 CS BT" bears S.39 1/4°W., 48.2 ft.

Note - Corner lies approx. 60 ft NW of paved logging Rd in young second growth timber. No trees suitable are within range North of corner.