

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 28 and 33

Alias _____ Description _____
 Alias _____ Description _____
 Alias _____ Description _____
 Alias _____ Description _____

Douglas County Surveyors Office - Randall Smith & Stephen
 Flause - 10/17/95 - C.S. 64/64 -4

-
- Mon Fd. - 3 1/4" Dia. Blm brass cap on a 2 1/2" O.D. by 30" long iron pipe. Found out of ground leaning against 72" dia. D.Fir stump.
 Corner position falls in a slide area (unable to occupy)
 - Bt's Fd. - 50" now 72" dia. 2 1/2' high rotting D.Fir stump, no bark scribing visible bears N.36°W., 8,7' (Orig rec. N.45°W., 5.9' dist is to bark, stump is big brg. difference are difficult to determine)
 10" now 19" dia. D.Fir with a fully healed blaze, bears S.9 1/2°W., 14.2'.
 10" now 15" dia. down and rotting D.Fir illegible scribe marks found, root hole near rec. bearing and distance (N55 1/2°W., 17.5' 1962 BLM)
 - Mon. Set - BLM BC/IP out of slide are west 15', marked "B01 15' east to corner reset DCSO 1995" are added to BLM BC/IP protrudes 9" above ground.
 - New Bt's - 15" dia D.Fir double blazed and scribed "1/4 S33 CS BT", bears S.6°W., 16.6'.
 14" dia. D.Fir double blazed and scribed "1/4 S33 CS BT", bears S68°E., 5.2'.
 18" Maple double blazed and scribed "1/4 S28 CS BT" bears N.32°W., 59.5'.
 72" D.Fir stump bears N.54 1/2°E., 12.1' (OBT)
 19" D.Fir bears, S.41 1/2°E., 18.7' (1962 BLM)