

PRIMARY CORNER DESCRIPTION Sec. cor. for 9, 10, 15 and 16

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO survey by W.H. Byars, under Contract #376, dated Jan. 22, 1881 - (DCSO records Vol. 4 Page(s) 1601)

Set Maple post for the cor. to secs. 9, 10, 15 and 16, from which

- A Maple 16" dia., bears N.80°E., 74 lks. dist.
- A Fir 36" dia., bears S.38°E., 124 lks. dist.
- A Fir 48" dia., bears S.89°W., 57 lks. dist.
- A Fir 48" dia., bears N.40°W., 154 lks. dist.

Douglas Co. Surveyors Office - Milo E. Godfrey, Deputy - M. Stone & V. Tracy, crew - Nov/Dec. 1962 - C.S. File 52/14-39

Found - 65" Fir S.89°W., 37.6 ft., old bark scribing visible.

- 44" Fir stump S.38°E., 81.8 ft., shows good scar.
- Old Fir snag, badly rotted, N.36°W., 88.4 ft. (Rec. brg. N.40°W., dist. is 134 lks., not 154 lks.)
- Wood scribing visible.

Clump of Maples N.80°E., 48.8 ft.

Set Brass cap at cor. mkd: County Surveyors Office

T 22 S R 8 W
S 9 | S 10
S 16 | S 15
1962

New BTs -20" D.Fir N.35°W., 67.2 ft. mkd. T22S R8W S9 CS BT
18" D.Fir North, 35.5 ft. mkd. T22S R8W S10 CS BT.
15" Maple S.10°E., 33.7 ft. mkd. T22S R8W S15 CS BT
Corner lies on steep NE slope approx. 100 ft. North of ridge top.

Mark Smalley - For: Roseburg Resources Co. - Dec. 2000 - M 132-59

Found - 1962 County brass cap on iron pipe.
76" Fir, S.89°W., 37.6 ft. bark scribed. Orig.
44" Fir, S.38°E., 81.8 ft. stump. Orig.
16" Maple, S.10°E., 33.7 ft. healed.
33" Fir, North 35.5 ft. stump.
35" Fir, N.35°W., 67.2 ft. stump.
New BTs- 12" Fir, N.60°E., 16.4 ft. "S 10 BT"
20" Fir, S.64°E., 36.8 ft. "S 15 BT"

Found OK by C. Sweeden, Jan. 2001 - M136-34