

PRIMARY CORNER DESCRIPTION Sec. Cor. for 2, 3, 10 and 11

Alias	_____	Description	_____
Alias	_____	Description	_____
Alias	_____	Description	_____
Alias	_____	Description	_____

GLO survey by W.H. Byars, under Contract #376, dated Jan. 22, 1881 - (DCSO records Vol. 4 Page(s) 1599)

-----

Set Fir post for cor. to secs. 2, 3, 10 and 11, from which

- A Fir 48" dia., bears N.50°E., 45 lks. dist.
- A Fir 36" dia., bears S.23°E., 50 lks. dist.
- A Fir 30" dia., bears S.32°W., 55 lks. dist.
- A Fir 30" dia., bears N.36°W., 43 lks. dist.

J. W. Cole - Witnesses: C.G. McNeel and W.H. Jones - Nov. 2, 1915 - Vol. 2 Pages 238-239; Record book #1 Page 239 (and "old" corner book, Page 25)

-----

Renew corner with a rock 12" x 12" x 16", from which the stumps of the original trees bear as follows:

- A Fir 48" dia., bears N.50°E., 45 lks. dist.
- A Fir 36" dia., bears S.23°E., 50 lks. dist.
- A Fir 30" dia., bears S.32°W., 35 lks. dist.
- A Fir 30" dia., bears N.36°W., 43 lks. dist.

No trees near.

Douglas Co. Surveyors Office - Milo E. Godfrey, Deputy - M. Stone & V. Tracy, crew - Sept/Oct. 1962 - C.S. File 52/14-36

-----

Found - 12" x 12" x 16" rock set by Cole in 1915. No other rocks in immediate vicinity. No marks found on rock.

- Stump hole and rotten remnants of Fir stump, N.36°W., 28.4 ft.
- Slight depression, could be stump hole, N.50°E., 29.7 ft.
- Slight depression, could be stump hole, S.23°E., 33.0 ft.

No trace of SW BT, location falls in roadway.

Cole's notes state that stumps were all that was left of BTs in 1915. Yellow tag on fence post, 48 ft. E. of rock, stating that sec. corner was 48 ft. West of tag.

Alongside rock at corner, Set brass cap mkd:

County Surveyors Office

T 22	S R 8	W
	S 3	S 2
	S 10	S 11

1962

New BTs -8" D.Fir N.41°E., 34.0 ft. mkd. T22S R8W S2 CS BT  
 12" D.Fir N.59°W., 77.3 ft. mkd T22S R8W S3 CS BT  
 7" D.Fir S.33½°W., 57.2 ft. mkd. T22S R8W S10 CSBT  
 No trees available SE of corner.

cont

TOWNSHIP 22 RANGE 08 POINT IDENTIFIER # 500600

PRIMARY CORNER DESCRIPTION Sec. cor. for 2, 3, 10 and 11

Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

Fd. and used in BLM resurvey by Brooks and Jelley, under Group #'s 514 and 350, surveyed June 1963/March 1965 (DCSO records, Vol. 33 Page 13691)

Fd. OK by Brooks and Peterson in BLM survey of Aug 1965/Dec. 1967 (DCSO records, Vol. 34 Page 14113)  
Fd. OK, May 1986 by Les Roberts, C.S. File 63/18-5(F)  
Fd. OK by John A. Farmer in BLM Corrective Resurvey - March/April 1993 (DCSO records, Vol. 51 Pg. 19551)  
Fd. OK by D. Edwards, Sept. 1999 - M133-39

BLM dependent resurvey by Aaron M Graham, Cadastral Surveyor, under Group 1910, surveyed June/July 1999. (DCSO recs. Vol. 53 Page(s) 20490-1)

-----  
From the cor. of secs. 2, 3, 10 & 11, monumented with & iron post, 1" diam., firmly set, projecting 6" above the ground, with brass cap mkd.  
T 22 S  
S 3 | S 2  
S 10 | S 11  
R 8 W  
1962  
from which bearing trees mkd. by Godfrey in 1962, reported by Brooks and Peterson  
A fir, 30" diam., bears N.40°E., 34.3 ft., with a healed blaze.  
A fir, 31" diam., bears S.33½°W., 57.4 ft., with a healed blaze.  
A fir, 29" diam., bears N.59°W., 76.5 ft., with a healed blaze. (Record, 77.2 ft.)  
No suitable trees available in sec. 11.  
From this point, Bureau of Land Management, Oregon State Office, Geodetic Control Station No. EC 41155, bears S.3°31'05"W., 152.24 feet (mean bearing and sea level dist.), monumented with an aluminum rod, 3/4" diam., firmly set, 6" below the surface of the ground, with aluminum cap mkd. EC41155 GPS 1993.