

TOWNSHIP 22 RANGE 09 POINT IDENTIFIER # 200340

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 19 and 20

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GL0 survey by W.H. Byars, Deputy Surveyor, under Contract #202, dated March 11, 1875, - (DCSO records Vol. 4 Page(s) 1629)

Set a boulder stone, 14 x 10 x 5, and made stone mound for ¼ sec. corner, from which
A Cedar 48" dia., bears N.50°E., 42 lks. dist.
A Cedar 48" dia., bears West, 15 lks. dist.

GL0 survey by W.H. Byars, Deputy Surveyor under contract # 274 survey dated Sept. 10, 1877 (DCSO records Vol. 4 Page(s) 1652)

Stone and witness trees all standing.

Douglas Co. Surveyors Office - James Byron, Deputy - Crew, Milo Godfrey; A. Bilow - Sept. 1958 - C.S. File 49/103-2

Found - 1½" Iron pipe at corner.
Orig. 48" now 60" Cedar, old face not grown over, scribed "¼S".
No trace of orig. NE BT, would be in old roadway.
I Do Not Set Brass Cap at Corner.
New BT - 12" Cedar bears N.70°W., 9.3 ft. scribed ¼ S19 CS BT
Bearing Object:
I chisel 4" + and B.O. on sandstone outcrop 4 ft. above creek bed, N.56½°E., 45.9 ft.
Corner in creek bed near South bank.

Douglas Co. Surveyors Office - Vernon "Ray" Tracy, Jack Heritage, V. Perron, crew - Jan. 9, 1968 - C.S. File 54/60-25

Found - 1½" Iron pipe at corner point.
Rock outcrop bears N.56½°E., 45.9 ft., chiseled "+B0" 4 ft. above creek.
Orig. 48" now 60" Cedar, West, 9.9 ft., scribe visible.
12" now 14" Cedar N.70°W., 9.3 ft. scribe visible on nearly healed blaze.
Set Brass cap at cor. mkd: County Surveyors Office
T 22 S R 9 W
¼ S 19 | S 20
1968

Deposit I.P. alongside.
New BT - 12" Alder S.62°E., 20.2 ft. mkd. ¼ S20 CS BT.
This corner lies on left bank of creek, course NW, old logging road is completely destroyed along creek bottom.