

PRIMARY CORNER DESCRIPTION West 1/4 Cor. Sec. 5 only

Alias	Description
_____	_____
_____	_____
_____	_____
_____	_____

BLM resurvey by Harvey Wofford; Wayne Rogers and Owen Chatters II, Cadastral Surveyors under Group #'s 811 and 1000 - surveyed Aug. 1973/Oct. 1979 - (DCSO records Vol. 40 Page(s) 16062)

Point for the ¼ sec. cor. of sec. 5 only, at proportionate distance.

Set an iron post, 28" long, 2½" dia., 24" in the ground, with brass cap mkd:

T 22 S R 9 W
¼ S 5
1974

from which

A Fir 40" dia., bears N.16¼°E., 115 lks. dist. mkd. ¼ S5 BT.

A Hemlock 13" dia., bears S.24 3/4°E., 74 lks. dist. mkd. ¼ S5 BT.

Corner is located at top of ascent, slopes E.

BLM Corrective Dependent resurvey by Stephen J. Malloy and John P. Farnsworth, Cadastral Surveyors, under Group #'s 1125 and 1226, surveyed Nov./Dec. 1982 - (DCSO records Vol. 47 Page(s) 17931)

Point for the ¼ sec. cor. of sec. 5 only, at proportionate dist. on the W. bdy. of sec. 5.

From this point, the ¼ sec. cor. of sec. 5 only, erroneously established by Wofford, etal, 1973-79, bears South, 0.255 chs. dist. monumented with an iron post, 2½" dia., firmly set, projecting 4" above ground, with brass cap mkd. and witnessed as described in the official record.

Remove the iron post, and at the true corner point, RESET the iron post, 28" long, 2½" dia., 24" in the ground, with brass cap mkd:

T 22 S R 9 W
¼ S 5
1983

from which bearing trees mkd. by Wofford, etal,

A Fir 44" dia., bears N.18½°E., 93 lks. dist. with healed blaze.

A Hemlock 14" dia., bears S.19½°E., 95 lks. dist. with scribe marks ¼ S5 BT visible on partially healed blaze.

Cor. Fd. and used in BLM sub. section survey by Joel Robb, under Group #1281, surveyed Aug/Oct. 1985 - (DCSO records, Vol. 48 Page 18199)