

PRIMARY CORNER DESCRIPTION So. Sec. cor. for 32 & 33 only, T21-9

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GLO survey by Alonzo Gesner, Deputy Surveyor, under Contract #608 -dated April 17, 1893 - (DCSO records Vol. 2 Page(s) 898-99)

Set sandstone 12 x 10 x 7 ins., 8" in the ground on point of spur, sloping South for cor. to secs. 32, 33, 4 and 5, marked with 4 notches on the E. and 2 notches on the W. edges, from which

- A Chinquapin 8" dia., bears N.37°E., 50 lks. dist. mkd. T21S R9W S33 BT.
- A Fir 12" dia., bears S.37°E., 104 lks. dist. mkd. T22S R9W S4 BT.
- A Fir 12" dia., bears S.34°30'W., 99 lks. dist. mkd. T22S R9W S5 BT.
- A Fir 24" dia., bears N.58°W., 105 lks. dist. mkd. T21S R9W S32 BT.

GLO survey by Elmer O. Worrick, Deputy Surveyor, under Contract #632, dated April 28, 1894 - (DCSO records Vol. 4 Page(s) 1672-73)

Intersected N. bdy. of T., 9.03 chs. W. of the corner to secs. 32 and 33, T21S, which is a stone 10 x 7 x 13 ins. above ground, firmly set, and mkd. with 2 notches on the W., and 4 notches on the E. sides, from which

- A Chinquapin 8" dia., bears N.37°E., 50 lks. dist. mkd. T21S R9W S33 BT.
- A Fir 8" dia., bears S.37°E., 104 lks. dist. mkd. T22S R9W S4 BT.
- A Fir 12" dia., bears S.34°30'W., 99 lks. dist. mkd. T22S R9W S5 BT.
- A Fir 24" dia., bears N.58°W., 105 lks. dist. mkd. T21S R9W S32 BT.

I destroyed marks on posts and BT on South.

V. W. Hosford - For: Evans Products Co. - Aug. 1954 - C.S. File 41/292 and M 10-80

I find the corner to sections 32 and 33. At this corner I found no trace of the original marked stone. The original mkd. NE BT is gone. The other 3 BTs are standing, but dead since the fire of 1951.

BLM resurvey by Joel E. Robb, Cadastral Surveyor, under Group #1281, surveyed Aug./Oct. 1985 - (DCSO records Vol. 48 Page(s) 18188)

(Cont. Next Page)

TOWNSHIP 22 RANGE 09 POINT IDENTIFIER # 309700

PRIMARY CORNER DESCRIPTION So. sec. cor. for 32 & 33 only, T21-9

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

At the corner of secs. 32 and 33 only, recovered and recorded by Hosford in 1954, determined from the remains of the original bearing trees:

A decayed Fir snag 22" dia., bears S.36°E., 102 lks. dist. no marks visible. (Rec. S.37°E., 104 lks.)

A sawed Fir stump 22" dia., bears S.34½°W., 99 lks. dist. with old axe marks visible on opened blaze.

A sawed Fir stump 47" dia., bears N.71°W., 105 lks. dist. no marks visible. (Rec. N.58°W.)

At the corner point

Set an iron post 28" long, 2½" dia., 8" in the ground, to solid rock, and in a mound of stone, 4 ft. base, to top, with brass cap mkd:

T 21 S R 9 W

S 32 S 33

1985

from which new bearing trees

A Fir 10" dia., bears N.72°E., 11 lks. dist. mkd. T21S R9W S33 BT.

A Fir 10" dia., bears N.38¼°W., 71 lks. dist. mkd. T21S R9W S32 BT.

The corner is located on a small spur, sloping S.

Fd. & used on Dependent resurvey by Boyd W. Peterson & John A. Farmer, Cadastral Surveyors, under Group #1791, surveyed Oct. 1995/Feb. 1998. (DCSO records Vol. 52 Page(s) 19859-60)