

PRIMARY CORNER DESCRIPTION No. 1/4 Cor. for Sec. 33 only

Alias	Description
Alias	Description
Alias	Description
Alias	Description

GLO survey by W.H. Byars, Deputy Surveyor, under Contract #279, dated March 5, 1878, - (DCSO records Vol. 4 Page(s) 1655)

Set a Fir post 4" dia., 4 ft. long, 20" in ground, for the ¼ sec. corner, from which,
A Fir 30" dia., bears S.10°W., 33 lks. dist.
A Fir 30" dia., bears N.75°W., 43 lks. dist.

BLM resurvey by Harvey Wofford; Wayne Rogers and Owen Chatters II, Cadastral Surveyors under Group #'s 811 and 1000 - surveyed Aug. 1973/Oct. 1979 - (DCSO records Vol. 40 Page(s) 16052-53)

Point for the ¼ sec. cor., at proportionate distance; there is no remaining evidence of the original corner.
Set an iron post, 28" long, 2 1/2" dia., 22" in the ground, with brass cap mkd:

¼ S 33
T 22 S R 9 W
1975

from which
A Fir 8" dia., bears S.82°E., 46 lks. dist. mkd. ¼ S33 BT.
A Fir 17" dia., bears S.60°W., 34 lks. dist. mkd. ¼ S33 BT

BLM Corrective Dependent resurvey by Stephen J. Malloy and John P. Farnsworth, Cadastral Surveyors, under Group #'s 1125 and 1226, surveyed Nov./Dec. 1982 - (DCSO records Vol. 47 Page(s) 17923)

Point for the ¼ sec. cor., at proportionate distance; there is no remaining evidence of the original corner.
From this point, the ¼ sec. cor. of sec. 33 only, erroneously reestablished by Wofford, etal, 1973-79, bears N.55°42'E., 0.15 chs. dist., monumented with an iron post, 2½" dia., firmly set, projecting 4" above ground, with brass cap mkd. and witnessed as described in the official record.

Remove the iron post, and at the true corner point, RESET the iron post, 28" long, 2½" dia., 24" in the ground, with brass cap mkd:

¼ S 33
T 22 S R 9 W
1984

from which the bearing trees mkd. by Wofford, etal,
A Fir 11" dia., bears N.89 ¾°E., 58½ lks. dist. with healed blaze.
A Fir 20" dia., S.67°W., 19½ lks. dist. with healed blaze.
