

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 21 and 22

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO survey by W.H. Byars, Deputy Surveyor, under Contract #202, dated March 11, 1875, - (DCSO records Vol. 4 Page(s) 1637)

Set a sandstone 16 x 12 x 5, for the 1/4 sec. corner, made stone mound. No timber near.

GLO survey by Elmer O. Worrick, Deputy Surveyor, under Contract #632, dated April 28, 1894 - (DCSO records Vol. 4 Page(s) 1710)

After diligent search, I was unable to find any trace of the 1/4 sec. corner, I therefore
Set a sandstone 20 x 12 x 10 ins., 16" in the ground on steep hillside sloping West for 1/4 sec. corner, mkd. 1/4 on the W. face, from which
 A Chinquapin 6" dia., bears East, 106 lks. dist. mkd. 1/4 S BT.
 An Alder 6" dia., bears S.83°W., 125 lks. dist. mkd. 1/4 S BT.

BLM resurvey by Harvey Wofford; Wayne Rogers and Owen Chatters II, Cadastral Surveyors under Group #'s 811 and 1000 - surveyed Aug. 1973/Oct. 1979 - (DCSO records Vol. 40 Page(s) 16049)

Point for the 1/4 sec. cor., at proportionate distance; there is no remaining evidence of the original corner.
Set an iron post, 28" long, 2 1/2" dia., 15" in the ground, and in a mound of stone, 3 ft. base, to top, with brass cap
mkd: T 22 S R 9 W
 1/4
 S 21 | S 22
 1975

from which
 A Fir 12" dia., bears N.36°E., 62 lks. dist. mkd. 1/4 S22 BT
 A Fir 17" dia., bears N.50°W., 24 lks. dist. mkd. 1/4 S21 BT

BLM Corrective Dependent resurvey by Stephen J. Malloy and John P. Farnsworth, Cadastral Surveyors, under Group #'s 1125 and 1226, surveyed Nov./Dec. 1982 - (DCSO records Vol. 47 Page(s) 17920)

The 1/4 sec. cor., monumented with the original sandstone, 16 x 12 x 8 ins., firmly set, 10" in the ground, mkd. 1/4 on W. face, alongside of which is an iron pipe, set by person(s) unknown, 1" dia., firmly set, projecting 2" above ground.
(Cont. Next Page)

TOWNSHIP 22 RANGE 09 POINT IDENTIFIER # 400340

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 21 and 22

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

From this point, the $\frac{1}{4}$ sec. cor. of secs. 21 and 22, erroneously reestablished by Wofford, etal, 1973-79, bears S.20°27'W., 1.007 chs. dist., monumented with an iron post, 2½" dia., firmly set, projecting 4" above ground, with brass cap mkd. and witnessed as described in the official record.

Remove the iron post, destroy the marks on the bearing trees, and at the true corner point

Reset the iron post, 28" long, 2½" dia., 24" in the ground, with brass cap mkd:

T 22 S R 9 W
 $\frac{1}{4}$
S 21 | S 22
1983

from which

A Fir 11" dia., bears N.87°E., 39 lks. dist. mkd. $\frac{1}{4}$ S22 BT

A Fir 20" dia., bears S.36°W., 29 lks. dist. mkd. $\frac{1}{4}$ S21 BT

Deposit corner stone and iron pipe alongside the iron post.

Survey by Les Roberts - For: International Paper Co. - Sept. 1983 - C.S. File 58/280 and M 90-52

(Condition report. This report filed previously to the approval of the above BLM corner visit)

Found - 1983 BLM brass cap.

10" x 12" x 16" stone mkd. " $\frac{1}{4}$ S" beside cap.

10" Fir bears S.88°E., 26.2 ft., scribe visible,
(Rec. N.87°E., 25.7 ft.)

20" Fir bears S.39°W., 19.0 ft., scribe visible.

Found OK by Neil Hibbs, 8/2025 - M185-39