

PRIMARY CORNER DESCRIPTION C C for Secs. 3 and 4 only

Alias	Description
Alias	Description
Alias	Description
Alias	Description

GLO survey by Elmer O. Worrick, Deputy Surveyor, under Contract #632, dated April 28, 1894 - (DCSO records Vol. 4 Page(s) 1666)

Set Hemlock post 4½ ft. long, 4" sq., 24" in ground, at the point of intersection for closing corner, to secs. 3 and 4. Marked C.C. on the S.; T22S S3 on the E.; R9W S4 on the W. faces, with 3 notches on the E. and W. sides, from which
A Fir 16" dia., bears S.24°E., 66 lks. dist. mkd. T22S R9W S3 BT.
A Fir 20" dia., bears S.43°W., 27 lks. dist. mkd. T22S R9W S4 BT.
A Fir 10" dia., bears N.21°30'W., 20 lks. dist. mkd. C.C. T22S R9W S3-4 BT.

V. W. Hosford - For: Evans Products Co. - Aug. 1954 - C.S. File 41/292 and M 10-80

The closing cor. to sections 3 and 4 is marked by a 1½" iron pipe with cap marked $\begin{matrix} S & 33 \\ S4 & | & S3 \end{matrix}$
The original SE BT is a living 36" tree with burned out scar. The other two original BTs are gone.

Douglas Co. Surveyors Office - John Powell, Deputy - Sept. 1971 - C.S. File 53/66-132

This cor. falls in old landing. Old BTs are close to cor., definitely lost by logging.

BLM resurvey by Joel E. Robb, Cadastral Surveyor, under Group #1367, surveyed April/June 1987 - (DCSO records Vol. 45 Page(s) 18429-30)

The closing cor. of secs. 3 and 4, perpetuated by person(s) unknown and recorded by Vernon W. Hosford, Registered Land Surveyor No. 253 in 1954, monumented with an iron post, 1½" dia., firmly set 6" below ground, with iron cap mkd. S3 S4 S33, from which the remains of an original bearing tree:
A decayed Fir stump 38" dia., bears S.24°E., 66 lks. dist. with scribe mark T visible on opened blaze.
At the corner point
Set a stainless steel post, 28" long, 2 1/2" dia., 24" in the ground, with brass cap mkd:
(Cont. Next Page)

PRIMARY CORNER DESCRIPTION C.C. for Secs. 3 and 4 only

Alias _____ Description _____
 Alias _____ Description _____
 Alias _____ Description _____
 Alias _____ Description _____

T 21 S R 9 W
 S 33
 S 4 | S 3
 T 22 S
 CC
 1987

from which new bearing trees
 A Fir 11" dia., bears S.10 3/4°E., 84½ lks. dist. mkd.
 T22S R9W S3 CC BT.
 A Fir 15" dia., bears S.61½°W., 55 lks. dist. mkd. T22S
 R9W S4 CC BT.
 Deposit white "DEEP-1" magnetic marker at base and the iron
 post alongside the stainless steel post.
 The corner is located 130 lks. S. of a ridge, bears E. and W.

Dependent resurvey by Boyd W. Peterson & John A. Farmer,
 Cadastral Surveyors, under Group #1791, surveyed Oct.
 1995/Feb. 1998. (DCSO records Vol. 52 Page(s) 19864-5)

 Intersect N. bdy. of township, true point for the closing
 corner of secs. 3 & 4.
 Set a stainless steel post, 28" long, 2½" diam., 24" in the
 ground, with brass cap mkd.

T 21 S R 9 W
 S 33
 S 4 | S 3
 CC
 T 22 S
 1996

from which
 A fir, 21" diam., bears S 65¼°E., 162½ lks., mkd. T22S R9W
 S3 CC BT.
 A fir, 20" diam., bears S.7 3/4°W., 37 lks., mkd. T22S R9W
 S4 CC BT.

Deposit a magnet in a white plastic case at the base of the
 stainless steel post.
 From this point, the original closing corner for secs. 3 and
 4, bears N.0°44'13" E., 0.148 chs.; monumented with an iron
 post, 2½" diam., firmly set, projecting 2" above ground, with
 brass cap mkd.

T 21 S R 9 W
 S 33
 S 4 | S 3
 T 22 S
 CC
 1987

from which bearing trees mkd. by Robb
 A fir, 13" diam., bears S.10 3/4°E., 84½ lks., with healed
 blaze.

continued next page

PRIMARY CORNER DESCRIPTION C C for Secs. 3 and 4 only

Alias	Description

A fir, 20" diam., bears S.61½°W., 55 lks., with healed blaze.
I add the marks AM and bury the iron post 6" below the surface of the ground.

Ronald L Rice - Oct. 2017 - C.S. File 65/99-10

Found - 3¼" BLM brass cap on iron pipe, dated 1996
All accessories and BLM 1987 brass cap lost to construction of logging road waste area.
SE corner Section 33, T21S R9W, Douglas County brass cap dated 1971 bears N.89°57'23"E., 233.02' (1998 BLM record 233.44')
Monument referenced & removed prior to construction of waste area.
Reset - 1996 BLM monument reset on top of waste area. Steel post adjacent to corner.
New - 5/8"x30" rebar with 2½" aluminum cap marked "RM4 2017 54633LS" set 3" below ground bears N.36°09'32"E., 93.31'. Monument located on south side of spur rd
5/8"x30" rebar with 2½" aluminum cap marked "RM3 2017 54633LS" set 3" below ground bears N.69°52'32"E., 175.33'. Monument located on south side of landing.
5/8"x30" rebar with 2½" aluminum cap marked "RM2 2017 54633LS" set 3" below ground bears N.46°44'09"E., 212.55'. Monument located on north side of main road.
5/8"x30" rebar with 2½" aluminum cap marked "RM1 2017 54633LS" set 3" below ground bears S.42°39'32"W., 102.74'. Monument located on south side of main road.
Note - Reference monuments have steel post adjacent to it. Location tag attached to post. Basis of bearing 1998 BLM Dependent Resurvey of Sections 3, 4, 9, 10, T22S, R9W, W.M.
Compass Declination Unknown