

TOWNSHIP 22 RANGE 09 POINT IDENTIFIER # 500240

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 26 and 27

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

From this point, the $\frac{1}{4}$ sec. cor., erroneously reestablished by Wofford, etal, 1973-79, bears N.7°44'E., 0.94 chs. dist. monumented with an iron post, 2 $\frac{1}{2}$ " dia., firmly set, projecting 4" above ground, with brass cap mkd. and witnessed as described in the official record.

Remove the iron post, destroy the marks on the bearing trees, and at the true point, reset the iron post 28" long, 2 $\frac{1}{2}$ " dia., 24" in ground with brass cap mkd:

T 22 S R 9 W

$\frac{1}{4}$
S 27 | S 26
1983

from which

A Fir 11" dia., bears N.81°E., 41 lks. dist. mkd. $\frac{1}{4}$ S26 BT
A Fir 27" dia., bears S.30 $\frac{3}{4}$ °W., 40 lks. dist. mkd. $\frac{1}{4}$ S27 BT.

From this same point, a point established by person(s) unknown, bears S.59 $\frac{1}{2}$ °E., 18 $\frac{1}{2}$ lks. dist. monumented with an iron pipe, 1 $\frac{3}{4}$ " dia., firmly set, projecting 14" above the ground.

The corner is located on steep SE. slope.