

TOWNSHIP 22 RANGE 12 POINT IDENTIFIER # 460340

PRIMARY CORNER DESCRIPTION Center East 1/16 Cor. Sec. 22

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

Survey by Robert B. Ward, Jr. - For: Champion International Corp. - Nov. 1981/June 1982 - M 92-58

Set a 2½" BC/IP with the following accessories:
10" Alder bears S.10°00'W., 13.0 ft. (1982 BT)
11" Alder bears N.89°00'W., 21.8 ft. (1982 BT)
Both bark scribed "CE 1/16 S22 BT"

Corner report by Burton W. Holt - C.S. File 58/290-3 (report filed with County April 6, 1984)

A road, to be constructed, would destroy this corner monument and its accessories. I, therefore, set three reference points and removed the monument.

After the road was constructed and surfaced with crushed rock, I reset the monument in its original position. This corner lies in a road bed at the intersection of two roads. I set the corner monument one foot below the road surface.

I Marked:
A 10" Alder which bears N.58°W., 23.8 ft. scribed "CE 1/16 S22 BT", attached a metal BT tag.

I set a 5/8" x 30" iron rod in the road cut which bears South, 42.2 ft., attached a metal BT tag.

This cor. monument is a 2½" iron pipe with brass cap mkd. CE 1/16 S22 LS 1091. Corner was originally set by R. Ward in June 1982.

Douglas Co. Surveyors Office - L.E. Monrean, Deputy - R.W. Smith, crew - Jan. 8, 1985 - C.S. File 62/25-2

Found - 1982 Brass cap monument at gravel road intersection, 8" below surface.

A 10" Alder, now a 12" dia., 6 ft. stump, bark scribed "CE 1/16 S22 BT" bears N.61½°W., 24.1 ft. (Rec. N.58°W., 23.8 ft.)

5/8" dia. Iron rod 15" high, bears South 42.7 ft. (Rec. 42.2 ft.)

BTs from M 92-58 evidently destroyed during road construction not found.

New Accessory:
Set 1/2" x 8" bridge spike into 48" dia. Cedar stump. Spike bears N.13°E., 94.7 ft. stamped "BO" and is set through a County Surveyor's BT tag. Stump is 4 ft. high on uphill side.