

PRIMARY CORNER DESCRIPTION East 1/4 Cor. for Sec. 26 only

Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

GLO survey by Wm. Thiel, Deputy Surveyor, under Contract #534, dated Jan. 12, 1889 (DCSO records Vol. 5 Page(s) 2024)

-----  
On East slope of spur, set a Hemlock post, 3 ft. long, 3" sq. 24" in the ground for ¼ sec. corner mkd. ¼S on West face, from which

- A Fir 36" dia., bears N.50°E., 10 lks. dist. mkd. ¼ S BT.
- A Fir 36" dia., bears N.5°W., 11 lks. dist. mkd. ¼ S BT.

GLO survey by Charles A. Slang, Deputy Surveyor, under Contract #793, dated Feb. 17, 1910 - (DCSO records Vol. 5 Page(s) 2100)

-----  
Intersect the old ¼ sec. cor. which is a post mkd. and witnessed as described by the Surveyor General. I change the cor. for Sec. 26 only. I destroy marks on E. side of post, from which

- A Fir 60" dia., bears N.23°W., 11 lks. dist. mkd. ¼ S26 BT
- A Cedar 10" dia., bears S.21°W., 26 lks. dist. mkd. ¼ S26 BT.

Survey by Arnold G. Gibson - For: Oregon State Board of Forestry - Lloyd D. Smith, Transitman - July 16, 1969 - C.S. File 55/101-14

-----  
Original Hemlock post, missing, from which a  
36" Fir bears N.50°E., 10 lks., missing.

36" Fir bears N.05°W., 11 lks.; now 43", in place.

Restoration by Slang in 1910:

Orig. Hemlock post, destroyed marks on E. side, now missing, from which a:

60" Fir bears N.23°W., 11 lks.; now 63", in place.

10" Cedar bears S.21°W., 26 lks.; now 12", in place, face partially closed, scribes ¼ visible.

Set 1½" x 36" galv. Iron pipe with 3" bronze cap mkd. "Ore. St. Bd. of Forestry ¼ S26 1969 RS 359", 34" in ground, and from which a:

11" Cedar bears S.66½°E., 14.6 ft. to face, scribed ¼ S26 BT RS 359.

12" Cedar, orig., bears S.21°W., 17.1 ft. to face, scribed BT.

Set 4x4x72" white painted cedar post 1.6 ft. South of corner pipe.

OSFD metal location poster on 11" Cedar S.66½°E., 14.6 ft.

(Cont. Next Page)

TOWNSHIP 22 RANGE 12 POINT IDENTIFIER # 600240

PRIMARY CORNER DESCRIPTION East 1/4 Cor. for Sec. 26 only

Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

Survey by Arnold G. Gibson - For: Oregon State Board of Forestry - Restored by Wm. Metcalf - Jan. 7, 1975 - C.S. File 58/31

-----

Original Hemlock post, missing, from which a:

36" Fir bears N.50°E., 10 lks.; missing.

36" Fir bears N.05°W., 11 lks.; uprooted windfall.

Restoration 1910: orig. Hemlock post, destroyed marks on E. side, now missing, from which a:

60" Fir bears N.23°W., 11 lks.; uprooted windfall.

10" Cedar bears N.21°W., 26 lks.; now 13" x 3 ft. high stub, in place, scribes  $\frac{1}{4}$  visible.

Restoration 1969: 1½" x 36" galv. I.P. with 3" bronze cap, found out of place in root wad of uprooted BT, 25 ft. downhill, from which a:

11" Cedar bears S.66½°E., 14.6 ft.; uprooted windfall.

4x4x72" WPCP bears South 1.6 ft.; found lying on ground knocked out of place by uprooted BT.

RESET above galv. I.P. with 3" bronze cap and re-marked "OREGON STATE BOARD OF FORESTRY T22S R12W 1/4 S26 1974 RS 359", 35" in ground and from which:

68" Fir bears N.22½°W., 35.1 ft. to face, scribed  $\frac{1}{4}$  S26 BT

59" Fir bears N.73°W., 32.6 ft. to face, scribed  $\frac{1}{4}$  S26 BT RS 359.

Set 4x4x72" white painted cedar post S.02°E., 4.8 ft. from corner pipe.

OSFD metal location poster on 68" Fir BT, N.22½°W., 35.1 ft.