

PRIMARY CORNER DESCRIPTION Center North 1/16 Sec. 13

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

Douglas Co. Surveyors Office - Randall Smith and Stephen
Flause, crew - Jan. 5, 1988 - C.S. File 62/49-5 (M101-35)

Found - 6"x6" concrete post with top leaning approx. 5"
southerly of plumb. Post protrudes 3 ft. above
ground mkd. "U.S." on East side. (Possibly set
by Lighthouse Service. See Dept of Commerce
letter between R.R. Tinkham, Supt. of
Lighthouses, and H.L. Eppstein, Co. Surveyor, in
C.S. File 18/20A dated Aug. 22, 1931.)

A 1¼" I.D. Iron pipe protruding 1.5 ft. above ground
inside a 2" I.D. Iron pipe protruding 1.0 ft.
above ground, source unknown. (noted as accessory
below)

Bearing and distances taken to plumb position of concrete
post:

30" now 36" dia., 8 ft. high broken and rotted
Spruce stump, scribing found "CS /16" bears
N.71°W., 3.2 ft. (Rec. West 2.3 ft. per M 1-74)

30" dia. Spruce, now down and tipped out of
position, root wad is near record bearing and
distance. (S.54°E., 16.0 ft.) (per M 66-64)

A 1¼" I.D. Iron pipe protruding 1.5 ft. above ground
inside a 2" I.D. Iron pipe protruding 1.0 ft.
above ground, bears S.5°E., 4.8 ft. (meas.
between approx. plumb position of concrete post
and I.P.s) (Rec. S.5°E., 3.8 ft. dist. to top of
I.P.s and concrete post per M 66-64) Source
unknown.

Steel post and paddle "Oregon State Park Boundary"
bears S.8°E., 2.4 ft. (Rec. South 2 ft. per M 66-
64)

31" now 37" dia. Spruce with a partially healed
single blaze and illegible scribe visible. We
open and find "CN 1/16 S13 BT" scribed in blaze,
bears N.2½°E., 21.6 ft. (N.9°E., 20.2 ft. per M
66-64)

New BT - 7" Hemlock double blazed and scribed "CN 1/16 S13
CS BT" bears S.88½°E., 26.4 ft.

FD. Ok by DCS0, July 2004, C.S. File 67/8